

**CP&L**

Carolina Power &amp; Light Company

May 31, 1978

*Central File*  
*50-261*

FILE: NG-3516(R)

SERIAL: GD-78-1387

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 818  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
RESPONSE TO I. E. BULLETIN NO. 78-05

Dear Mr. O'Reilly:

An investigation has been completed which confirmed that there are no General Electric Model CR105X auxiliary contract mechanisms used at H. B. Robinson Unit No. 2.

Yours very truly,

E. E. Utley  
Senior Vice President  
Power Supply

RSM/DCS:jfc

cc: Mr. E. Volgenau