

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-261 H.B. Robinson 2

DOC DATE: 781023

RECIPIENT: O'Reilly, J.P.

ACCESSION NBR: 7810310143

ORIGINATOR: Banks, H.R.

COPIES RECEIVED:

COMPANY NAME: Carolina Pwr & Light

LTR 1 ENCL 1

SUBJECT:

SIZE: 1+2

LER#78-023/03L-0 on 780922: while proceeding from Hot to Cold Shutdown the concentration of boric acid storage tank B was 22796 ppm, due to insufficient sampling during batching, & tank A level was low as a result of borating the RCS.

DISTRIBUTION CODE: A002

NOTARIZED

DISTRIBUTION TITLE:
INCIDENT REPORTS

NAME

ENCL?

FOR ACTION

BR CHIEF

W/4 ENCL

ORB#1 BC

REG FILE

W/ENCL

NRC PDR

W/ENCL

I & E

W/2 ENCL

MIPC

W/3 ENCL

I & C SYSTEMS BR

W/ENCL

NOVAK/CHECK

W/ENCL

EEB

W/ENCL

AD FOR ENG

W/ENCL

PLANT SYSTEMS BR

W/ENCL

HANAUER

W/ENCL

AD FOR PLANT SYSTEMS

W/ENCL

AD FOR SYS & PROJ

W/ENCL

REACTOR SAFETY BR

W/ENCL

ENGINEERING BR

W/ENCL

KREGER/J. COLLINS

W/ENCL

POWER SYS BR

W/ENCL

K SEYFRIT/IE

W/ENCL

LPDR

W/ENCL

NSIC

W/ENCL

ACRS

W/16 ENCL

TOTAL NUMBER OF COPIES REQUIRED:

LTR
ENCL

42
42

NOTES:

NOV 1 1978



Carolina Power & Light Company

October 23, 1978

FILE: NG-3516 (R)

SERIAL: GD-78-2819

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

REGULATORY DOCKET FILE COPY

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 78-23

Dear Mr. O'Reilly:

In accordance with Section 6.9.2.b of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

DCS:jpw*

Attachment

cc: Messrs. R. A. Hartfield
J. G. Davis

781031.0143

A002
5/11