

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9211050019 DOC. DATE: 92/10/28 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co 05000261
 AUTH. NAME: DIETZ, C.R. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC 920908 ltr transmitting SALP rept covering evaluation period of 920331-0627 & discussions during NRC presentation of SALP rept on 920924. Util encouraged w/ improvements in areas of plant operations & security.

DISTRIBUTION CODE: IE40D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Systematic Assessment of Licensee Performance (SALP) Report

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 LA	1 0	PD2-1 PD	1 1
	MOZAFARI, B	1 1		
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	COMMISSION	5 5	DEDRO	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LHFBPT	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DREP/PEPB9D	1 1	NRR/DREP/PRPB11	1 1
	NRR/DRIS/RSGB9D	1 1	NRR/DRIS/RSIB9A	1 1
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	OGC/HDS2	1 1
	<u>REG FILE</u> 02	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G/BRYCE, J.H.	1 1	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 29 ENCL 28



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550

091 2 8 1992

Robinson File No.: 13510C

Serial: RNPDP/92-2849

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

H. B. Robinson Steam Electric Plant, Unit No. 2
Docket No. 50-261
License No. DPR-23
Response to NRC Systematic Assessment of Licensee Performance

Gentlemen:

Carolina Power and Light Company (CP&L) has received and reviewed the Systematic Assessment of Licensee Performance (SALP) transmitted by letter dated September 8, 1992. This report provided results from the evaluation period of March 31 through June 27, 1992. Also, CP&L had the benefit of comment and discussion during the NRC presentation of the SALP Report at our facility on September 24, 1992.

CP&L is pleased with the quantitative ratings of the SALP Board which reflect that the overall performance of H. B. Robinson was good and is improving. It is encouraging that acknowledgment was made of significant improvement in the area of plant operations and sustained superior performance in radiological controls and plant security.

The staff at H. B. Robinson Unit 2 is aware of the functional areas where performance was characterized as "mixed", and acknowledge that further management focus and attention is necessary to obtain superior performance in these areas. We recognize that the SALP ratings received depend to a certain degree on effective and timely implementation of future corrective actions, and we are committed to meeting these obligations. For areas where corrective actions are being developed or issues are being addressed, we are dedicated to completing these activities and providing auditable results.

03:108

9211050019 921028
PDR ADOCK 05000261
Q PDR

IF 40
1/0


United States Nuclear Regulatory Commission

Serial: RNPD/92-2849

Page 2 of 2

In closing, the observations and recommendations of the SALP Board are appreciated, and will be used in our continuing process of evaluating and improving overall performance. CP&L will continue to strive for excellence in the safe and reliable operation of H. B. Robinson Unit 2.

Very truly yours,



C. R. Dietz
Vice President

Robinson Nuclear Project Department

RDC:sgk

cc: Mr. S. D. Ebnetter
Mr. L. W. Garner