

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8003280535 DOC.DATE: 80/03/25 NOTARIZED: NO DOCKET #
 FACIL:50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Ligh 05000261
 AUTH.NAME AUTHOR AFFILIATION
 UTLEY,E.E. Carolina Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 SCHWENCER,A. Operating Reactors Branch 1


SUBJECT: Informs that util will comply w/QA guidelines for fire protection items specific in Section 1.0 of Reg Guide 1.120 & inadvertently omitted from 800318 response. Fire protection QA program will comply w/guidelines by 801031.

DISTRIBUTION CODE: A006S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
 TITLE: Fire Protection Information (After Issuance of OP. Lic.)

NOTES:-----

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
ACTION:	05 BC <u>ORB #1</u>	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	12 AUXIL SYS BR	2	2
	14 PLANT SYS BR	5	5	19 WAMBACH	1	1
	20 MURANAKA,R	1	1	OELD	1	0
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	22 ACRS	16	16			

APR 2 1980



MA
4



Carolina Power & Light Company

March 25, 1980

File: NG-3514(R)

SERIAL NO.: NO-80-472

Office of Nuclear Reactor Regulation
Attention: Mr. Albert Schwencer, Chief
Operating Reactors Branch No. 1
United States Nuclear Regulatory Commission
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
FIRE PROTECTION PROGRAM

Dear Mr. Schwencer:

Your letter of February 21, 1980 requested additional information and commitments concerning the fire protection program at H. B. Robinson. Our letter of March 18, 1980 responded to that request. One item, however, was inadvertently left out of that response. You had requested that Carolina Power & Light Company (CP&L) commit to comply with the quality assurance requirements for fire protection items as specified in Section 1.0 of Regulatory Guide 1.120, "Fire Protection Guidelines for Nuclear Power Plants." This letter is to inform you that CP&L will comply with the guidelines specified in Section 1.0 of Regulatory Guide 1.120 at H. B. Robinson. The Fire Protection Quality Assurance Program will be altered to comply with those guidelines by October 31, 1980.

If you have any questions on this subject, please contact our staff.

Yours very truly,

E. E. Utley
Executive Vice President
Power Supply and Customer Services

JJS/jc (880-141)

A006
S
1/0