

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8211090295 DOC. DATE: 82/11/04 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261  
 AUTH. NAME AUTHOR AFFILIATION  
 ZIMMERMAN, S. R. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 VARGA, S. A. Operating Reactors Branch 1

SUBJECT: Forwards "PWR Safety & Relief Valve Adequacy Rept," per  
 NUREG-0737, Item II.D.1.2. Rept confirms ability of safety &  
 relief valves to open & close under expected operating  
 fluid conditions.

DISTRIBUTION CODE: A046S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+32  
 TITLE: OR Submittal: TMI Action Plan Rgmt NUREG-0737 & NUREG-0660

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
NRR ORB1 BC 01	7 7		
INTERNAL: ELD/HDS1	1 0	IE/DEP DIR 33	1 1
IE/DEP EPDS	1 1	IE/DEP/EPLB	3 3
NRR/DHFS/DEPY29	1 1	NRR/DL DIR 14	1 1
NRR/DL/ADL 16	1 1	NRR/DL/ADOR 15	1 1
NRR/DL/ADSA 17	1 1	NRR/DL/ORAB 18	3 3
NRR/DSI/ADRP 26	1 1	NRR/DSI/ADRS 27	1 1
NRR/DSI/AEB	1 1	NRR/DSI/RAB	1 1
NRR/DST DIR 30	1 1	REG FILE 04	1 1
RGN2	1 1		
EXTERNAL: ACRS 34	10 10	FEMA-REP DIV	1 1
INPO, J. STARNES	1 1	LPDR 03	1 1
NRC PDR 02	1 1	NSIC 05	1 1
NTIS	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 43



Carolina Power & Light Company

NOV 04 1982

Office of Nuclear Reactor Regulation  
ATTN: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
NUREG-0737, ITEM II.D.1.2 - SAFETY  
AND RELIEF VALVE ADEQUACY REPORT

Dear Mr. Varga:

As requested in NUREG-0737, Item II.D.1.2, Safety and Relief Valve Adequacy, Carolina Power & Light Company (CP&L) hereby submits the Safety and Relief Valve Adequacy Report for the H. B. Robinson Steam Electric Plant Unit 2 (HBR2). The report is enclosed for your review.

This report indicates that the safety and relief valves, piping arrangements and fluid inlet conditions for HBR2 are bounded by the valves and test parameters and confirm the ability of the safety and relief valves to open and close under the expected operating fluid conditions.

If you have any questions regarding this report, please contact a member of my staff.

Yours very truly,

S. R. Zimmerman  
Manager  
Licensing & Permits

SRZ/lr (5680C4T4)  
Enclosure

cc: Mr. J. P. O'Reilly (NRC-RII)  
Mr. G. Requa (NRC)  
Mr. Steve Weise (NRC-HBR)

B211090295 B21104  
PDR ADOCK 05000261  
P PDR

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

A046