

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9111250153      DOC. DATE: 91/11/18      NOTARIZED: NO      DOCKET #  
FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co      05000261  
AUTH. NAME      AUTHOR AFFILIATION  
FLOYD, S.D.      Carolina Power & Light Co.  
RECIP. NAME      RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: Suppls 900126 & 910308 responses to Generic Ltr 89-13, "Svc Water Sys Problems Affecting Safety-Related Equipment." All activities associated w/generic ltr completed during Refueling Outage 13.

DISTRIBUTION CODE: A065D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
TITLE: Generic Ltr 89-13 - Svc Water Sys Problems Affecting Safety-Related E

### NOTES:

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	LO, R	1	1			
INTERNAL:	CHU, A NRR/PD1-3	1	1	REG FILE	1	1
EXTERNAL:	NRC PDR	1	1	NSIC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 5 ENCL 5-0

MAY

**Carolina Power & Light Company**

**Nuclear Services Department**

411 Fayetteville Street Mall - P.O. Box 1551  
Raleigh, North Carolina 27602

November 18, 1991

SERIAL: NLS-91-300

United States Nuclear Regulatory Commission  
ATTENTION: Document Control Desk  
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261/LICENSE NO. DPR-23  
SUPPLEMENTAL RESPONSE TO NRC GENERIC LETTER 89-13  
SERVICE WATER SYSTEM PROBLEMS AFFECTING SAFETY-RELATED EQUIPMENT

Gentlemen:

The purpose of this letter is to provide notification that the activities required by NRC Generic Letter 89-13, "Service Water System Problems Affecting Safety-Related Equipment," have been completed for the H. B. Robinson Steam Electric Plant, Unit No. 2 (HBR2). On July 18, 1989, the NRC issued Generic Letter 89-13, establishing extensive recommended actions in five major areas relative to monitoring and surveillance, testing, and design review of service water systems. Carolina Power & Light Company (CP&L) responded to Generic Letter 89-13 on January 26, 1990 indicating, with certain clarifications, our intent to comply with the letter and to complete the initial activities by start-up from the next scheduled refueling for each of the CP&L units.

CP&L submitted a supplemental response to Generic Letter 89-13 on March 8, 1991, describing extensive and aggressive actions taken at HBR2 during Refueling Outage No. 13 to address the tasks associated with the Generic Letter. The supplemental response provided a detailed review of the Generic Letter recommendations and the status of their implementation at HBR2. In summary, Items I(a), I(b), I(d), IV, and V were identified as complete; Items II and III as essentially complete; and work on Item I(c) as continuing. Further, the supplemental response stated that the remaining activities were scheduled for completion by September 30, 1991.

This letter provides our notification that the remaining activities identified in our March 8, 1991 response are now complete. The significant service water work activities completed during Refueling Outage No. 13, as well as the actions taken in response to Generic Letter 89-13, have resulted in a significant enhancement to the performance of the HBR2 service water system.

If you have questions or require additional information on this issue, please contact Mr. Lewis Rowell at (919) 546-2770.

Yours very truly,

*S. D. Floyd*

S. D. Floyd  
Manager

Nuclear Licensing Section

9111250153 911118  
PDR ADOCK 05000261  
PDR

LSR/dsm (1386RNP)

cc: Mr. S. D. Ebnetter  
Mr. L. Garner  
Mr. R. Lo

250067

Abb5 1/0