

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8812020238 DOC. DATE: 88/11/28 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 LOFLIN, L.I. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Confirms 881117 discussion re 881012 request for alternative schedule to perform actions required by Bulletin 88-009.

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response (50 DKT)

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-1 LA		1	0		PD2-1 PD		1	1
	LO, R		1	1					
INTERNAL:	AEOD/DOA		1	1		AEOD/DSP/TPAB		1	1
	NRR/ALEXION, T		1	1		NRR/DEST/ADE 8H		1	1
	NRR/DEST/ADS 7E		1	1		NRR/DEST/MEB 9H		1	1
	NRR/DOEA/EAB 11		1	1		NRR/DOEA/GCB 11		1	1
	NRR/DREP/EPB 10		1	1		NRR/PMAS/ILRB12		1	1
	NUDOCS-ABSTRACT		1	1		REG FILE 02		1	1
	RES/DSIR/EIB		1	1		RGN2 FILE 01		1	1
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 19

A/0-1 *[Signature]*

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



Carolina Power & Light Company

NOV 28 1988

SERIAL: NLS-88-275

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
CONFIRMATION OF DISCUSSIONS REGARDING NRC BULLETIN 88-09

Gentlemen:

This is to confirm a discussion on November 17, 1988 between Mr. Ronnie Lo (NRC) and Mr. Jan Kozyra (CP&L) regarding CP&L's request, dated October 12, 1988, for an alternative schedule to perform the actions required by NRC Bulletin 88-09.

As discussed, the NRC concurs in our request to postpone the thimble tube inspection requirements until Refueling Outage 13 during 1990.

Questions regarding this matter may be referred to Mr. R. W. Prunty at (919) 836-7318.

Yours very truly,

L. I. Loflin
Manager

Nuclear Licensing Section

JSK/crs (128CRS)

cc: Mr. M. L. Ernst
Mr. R. Lo
Mr. L. Garner (NRC - HBR)

8812020238 881128
PDR ADOCK 05000261
P PDC

TEI
110