

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8109180006 DOC. DATE: 81/09/15 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME: UTLEY, E. E. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIP. NAME: EISENHUT, D. G. RECIPIENT AFFILIATION: Division of Licensing

SUBJECT: Advises that NUREG-0737 Items II.B.3, II.F.1 & II.K.3, committed to in 801215 ltr, will now be completed by early Spring, 1982.

DISTRIBUTION CODE: A046S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Response to NUREG -0737/NUREG-0660 TMI Action Plan Rmpts (OL's)

NOTES:

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME	LTTR
ACTION:	ORB #1 BC	05	7	7			
INTERNAL:	A/D C&C SYS	27	1	1	A/D C&S ENG	22	1
	A/D FOR TECH	32	1	1	A/D GEN PROJ	31	1
	A/D LICENS	16	1	1	A/D M&Q ENG	23	1
	A/D OP REACT	15	1	1	A/D PLANT SYS	25	1
	A/D RAD PROT	26	1	1	A/D SAFETY AS	17	1
	DEP DIR, DHFS	29	1	1	DIR, EM PREP	33	1
	DIRECTOR, DE	21	1	1	DIRECTOR, DHFS	28	1
	DIRECTOR, DL	14	1	1	DIRECTOR, DSI	24	1
	DIRECTOR, DST	30	1	1	I&E	12	2
	IEVEPDBI		1	1	IEVEPLB		1
	DELD		1	1	OR ASSESS BR	18	3
	PDR	02	1	1	RAD ASMT BR		1
	REG FILE	01	1	1			
EXTERNAL:	ACRS	34	16	16	FEMA-REP DIV		1
	INPO, J. STARNES		1	1	LPDR	03	1
	NSIC	04	1	1	NTIS		1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 56 ENCL 9



Carolina Power & Light Company

September 15, 1981



FILE: NG-3514(R)

Serial No.: NO-81-1506

Mr. Darrell G. Eisenhut, Director
Division of Licensing
United States Nuclear Regulatory Commission
Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
NUREG-0737 JANUARY 1, 1982 ITEMS

Dear Mr. Eisenhut:

By letter dated December 15, 1980, Carolina Power & Light Company (CP&L) committed to complete several NUREG-0737, "Clarification of TMI Action Plan Requirements" Items by January 1, 1982 at its H. B. Robinson Steam Electric Plant, Unit No. 2. However, due to an increased workload necessitated by an unforeseen outage and steam generator repair at the Robinson Plant, five of the items committed to in the December 15, 1980 letter will not be completed by the January 1, 1982 required date. These items are shown in the table below:

<u>Item</u>	<u>Title</u>	<u>Description</u>
II.B.3	Post Accident Sampling	2. Plant Modifications*
II.F.1	Accident Monitoring	1. Noble Gas Monitor
II.F.1	Accident Monitoring	2. Iodine/particulate Sampling
II.F.1	Accident Monitoring	3. Containment High Range Monitor
II.F.2	Instrumentation for Detection of Inadequate Core Cooling	3. Install Level Instrument*
II.K.3	Final Recommendations, B & O Task Force	25. Power on Pump Seals


*Installation requires an outage.

These items will be completed during the next refueling outage, currently scheduled for early Spring, 1982.

AOAB
5/10

If you have any questions concerning these items, please contact our staff.

Yours very truly,



E. E. Utley
Executive Vice President
Power Supply and
Engineering & Construction

JHE/lr (2731)

cc: Mr. J. P. O'Reilly (NRC-RII)
Mr. J. D. Neighbors (NRC)