




Carolina Power & Light Company

APR 01 1982

Office of Nuclear Reactor Regulation
ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
United States Nuclear Regulatory Commission
Washington, D.C. 20555



H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
ADDITIONAL INFORMATION REQUEST - IE BULLETIN 80-04

Dear Mr. Varga:

Your letter of March 16, 1982 transmitted replacement enclosures for the additional information regarding the analysis of a main steam line break with continued feedwater addition. Your March 16 letter indicated that we should provide this information within the 30-day extension period which we had requested in our letter of February 25, 1982. Our February 25, 1982 letter did not request a 30-day extension. Rather, it indicated that due to the additional scope and analytical work, requiring off-site assistance and the on-going 10-year ISI outage, we would respond prior to September 1, 1982. Our schedule for responding remains as indicated in our February 25, 1982 letter, a copy of which is enclosed.

If you have any questions, please contact our staff.

Yours very truly,

S. R. Zimmerman
Manager
Licensing & Permits

DLB/lr (n-13)
Enclosure

cc: Mr. J. P. O'Reilly (NRC-RII)
Mr. G. Requa (NRC)

Acc'd
1/1

8204060116 820401
PDR ADOCK 05000261
G PDR



Carolina Power & Light Company

FEB 25 1982

RC/A-2

Office of Nuclear Reactor Regulation
ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
ADDITIONAL INFORMATION REQUEST FOR I.E. BULLETIN 80-04

Dear Mr. Varga:

Summary

In your letter of January 21, 1982, you requested additional information regarding our analysis of a main steam line break with continued feedwater addition (I.E. Bulletin 80-04). This letter requests an extension of the 30 days allowed for a response.

Details

We have reviewed our original analysis and have determined that additional analytical work is required to address your questions. This work will require off-site assistance. H. B. Robinson will begin its 10 year ISI - Refueling outage in March, 1982. This outage, which should be completed by June, 1982, will require significant plant and additional off-site resources. In light of the required scope of work to address your questions, CP&L requests an extension of the response date to September 1, 1982. This extension will enable us to prepare a complete, accurate and thorough response.

If you have any questions, please contact my staff.

Yours very truly,

S. R. Zimmerman
Manager
Licensing & Permits

FMG/DCW/lr (4656)

cc: Mr. J. P. O'Reilly (NRC-RII)
Mr. W. J. Ross (NRC-ONRR)

Dupe of

8203020479