

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8510240385 DOC. DATE: 85/10/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light Co. 05000261  
 AUTH. NAME AUTHOR AFFILIATION  
 ZIMMERMAN, S.R. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Forwards Rev 0 to Plant Emergency Procedure PEP-355, "Core Damage Assessment," per util 850624 commitment. Procedure incorporates Westinghouse Owners Group methodology re use of post-accident sampling sys, per TMI Action Item II.B.3.

*Revised 10/28/85 JH (pages inserted)*  
 DISTRIBUTION CODE: A046D COPIES RECEIVED: LTR ENCL 1 SIZE: 1+67  
 TITLE: OR Submittal: TMI Action Plan Rgmt NUREG-0737 & NUREG-0660.

NOTES:

05000261

OL: 07/31/70

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
NRR ORB1 BC 01	7 7		
INTERNAL: ACRS 34	10 10	ADM/LFMB	1 0
ELD/HDS1	1 0	IE/DEPER DIR 33	1 1
IE/DEPER/EPB	3 3	NRR PAULSON, W.	1 1
NRR/DHFS DEPY29	1 1	NRR/DL DIR 14	1 1
NRR/DL/ORAB 18	3 3	NRR/DSI/ADRS 27	1 1
NRR/DSI/AEB	1 1	NRR/DSI/ASB	1 1
NRR/DSI/RAB	1 1	NRR/DST DIR 30	1 1
REG FILE 04	1 1	RGN2	1 1
EXTERNAL: 24X	1 1	LPDR 03	1 1
NRC PDR 02	1 1	NSIC 05	1 1



Carolina Power & Light Company

OCT 2 1 1985

SERIAL: NLS-85-365

NRC TAC #44474

Director of Nuclear Reactor Regulation  
Attention: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Division of Licensing  
United States Nuclear Regulatory Commission  
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261/LICENSE NO. DPR-23  
PLANT EMERGENCY PROCEDURE - CORE DAMAGE ASSESSMENT  
NUREG-0737 - ITEM II.B.3

Dear Mr. Varga:

Enclosed is a copy of Plant Emergency Procedure No. 355 (PEP-355), "Core Damage Assessment" for Carolina Power & Light Company's (CP&L) H. B. Robinson Steam Electric Plant, Unit No. 2. This procedure incorporates the approved Westinghouse Owners' Group (WOG) methodology relating to the use of the Post Accident Sampling System to evaluate Core Damage. This is in accordance with the requirements of TMI Action Item II.B.3. Transmittal of this procedure prior to the upcoming emergency drill fulfills the CP&L commitment documented in CP&L letter NLS-85-205, dated June 24, 1985.

It should be recognized that the attached procedure is the most current version. Further changes may be determined necessary if the WOG methodology changes and/or improvement to the procedure is necessary.

If you have any questions concerning this transmittal, please contact Mr. Stephen D. Floyd at (919) 836-6901.

Yours very truly,


S. R. Zimmerman  
Manager

Nuclear Licensing Section

SRZ/MDM/mf (2013MDM)

Enclosure

cc: Dr. J. Nelson Grace (NRC-RII)  
Mr. G. Requa (NRC)  
Mr. H. Krug (NRC Resident Inspector - RNP)



A046  
11