

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: B606030074 DDC DATE: 86/05/30 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261  
 AUTH. NAME AUTHOR AFFILIATION  
 ZIMMERMAN, S. R. Carolina Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 RUBENSTEIN, L. S. PWR Project Directorate 2

SUBJECT: Forwards marked-up list of completion or implementation  
 dates for generic issues, per G Requa B60430 request.  
 Supplemental response will be provided by B60630.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 8  
 TITLE: DR Submittal: General Distribution

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
PWR-A ADTS		1	0	PWR-A EB		1	1
PWR-A EICSB		2	2	PWR-A FOB		1	1
PWR-A PD2 PD 01		5	5	REQUA, G		1	1
PWR-A PSB		1	1	PWR-A RSB		1	1
INTERNAL: ADM/LFMB		1	0	ELD/HDS1		1	0
NRR/DHFT/TSCB		1	1	NRR/ORAS		1	0
<u>REG FILE</u> 04		1	1	RGN2		1	1
EXTERNAL: 24X		1	1	EG&G BRUSKE, S		1	1
LPDR 03		1	1	NRC PDR 02		1	1
NSIC 05		1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 20



Carolina Power & Light Company

SERIAL: NLS-86-195

MAY 30 1986

Director of Nuclear Reactor Regulation  
Attention: Mr. Lester S. Rubenstein, Director  
PWR Project Directorate #2  
Division of PWR Licensing - A  
United States Nuclear Regulatory Commission  
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261/LICENSE NO. DPR-23  
IMPLEMENTATION OF GENERIC ISSUES

Dear Mr. Rubenstein:

Mr. Glode Requa's letter dated April 30, 1986, requested assistance in developing a listing of completion or implementation dates for generic issues at H. B. Robinson Steam Electric Plant, Unit No. 2.

The time required to gather and verify the information necessary for a complete response requires an extension of the submittal date. We have been able to provide confirmation of many "LIC ACT COMPLETE" listings. A markup showing this interim response is attached. A supplemental response will be provided by June 30, 1986.

Yours very truly,

S. R. Zimmerman  
Manager

Nuclear Licensing Section

JSK/pgp (3942JSK)

Attachment

cc: Dr. J. Nelson Grace (NRC-RII)  
Mr. G. Requa (NRC)  
Mr. H. Krug (NRC Resident Inspector - RNP)

8606030074 860530  
PDR ADOCK 05000261  
P PDR

A001  
1/1

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

03/31/88

CILITY: ROBINSON 2

ANT LOCATION: 5 MI NW OF HARTSVILLE, SC  
CKET NUMBER: 050-00261  
CH/ENGINEER: EBASCO  
INSPECTOR: H. KRUGLICENSED POWER: 2300 MWT  
DESIGN POWER: 0700 MWE  
NSSS VENDOR: WESTPROJECT MANAGER: G. REQUA  
BRANCH CHIEF: L. RUBENSTEIN  
LIC. ASSISTANT: . VACANT

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE	
				STATUS	DATE
08299	A-01	10 CFR 50.55 A(G) - ISI	01/01/70C		
06989	A-01	10 CFR 50.55 A(G) - ISI	08/31/83C	OK	
08126	A-02	APPENDIX I - ALARA	10/04/84C		
07407	A-03	SECURITY REVIEWS-MODIFIED AMENDMENT PLANS	02/27/79C		
01954	A-04	APPENDIX J - CONTAINMENT LEAK TESTING	12/28/81C		
01388	A-09	PRESSURE VESSEL BELTLINE MATERIAL SURVEILLANCE	05/19/80C		
00489	A-10	CONTINGENCY PLANNING	10/06/80C		
00488	A-11	GUARD TRAINING PLANS	08/03/81C	OK	
00490	A-12	VITAL AREA ANALYSIS	04/12/82C		
02755	A-15	QUALITY ASSURANCE REQUEST REGARDING DIESEL GENERAT	11/20/81C	OK	
01127	A-17	INSTRUMENTATION TO FOLLOW THE COURSE OF AN ACCIDEN	05/14/87	open	
004619	A-18	TECH SPECS AFFECTED BY 50.72 AND 50.73 (GL 83-43)	03/15/85C	OK	
009135	A-20	10 CFR 50.62 OPERATING REACTOR REVIEWS	N/S /		
009977	A-21	10 CFR 50.61, PRESSURIZED THERMAL SHOCK RULE			
007904	B-01	DIESEL GENERATOR LOCKOUT	01/19/81C	OK	
006467	B-02	FIRE PROTECTION	02/28/78C		
008397	B-03	PWR MODERATOR DILUTION	02/27/79C		
006709	B-04	REACTOR VESSEL OVERPRESSURE PROTECTION	09/14/79C		
007807	B-07	STEAM GENERATOR FEEDWATER FLOW INSTABILITY	07/09/80C	OK	
006424	B-12	STEAM GENERATOR TUBE INSPECTION	09/01/78C		

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

03/31/80

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
1159	B-12	STEAM GENERATOR TUBE INSPECTION	11/17/79C OK		
8505	B-14	CEA GUIDE TUBE WEAR	05/04/81C OK		
7792	B-16	EMERGENCY PLANNING AND REVISIONS	09/11/80C		
8508	B-17	TECH SPEC SURVEILLANCE FOR HYDRAULIC SNUBBERS	03/03/82C OK		
0271	B-20	CONTAINMENT LEAKAGE DUE TO SEAL DETERIORATION	08/25/80C		
0335	B-21	LOSS OF 125-V DC BUS VOLTAGE WITH LOSS OF ANNUNCIA	02/28/82C		
8511	B-22	TECH SPEC SURVEILLANCE REQUIREMENTS FOR MECHANICAL	03/25/84C		
0049	B-23	DEGRADED GRID VOLTAGE	09/19/80C OK		
8994	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POW	03/21/80C OK		
2560	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POW	12/05/83C OK		
0233	B-26	INADVERTANT SAFETY INJECTION DURING COOLDOWN	09/14/79C		
8356	B-32	BLOCKED SI SIGNAL DURING COOLDOWN	06/12/80C OK		
9414	B-32	BLOCKED SI SIGNAL DURING COOLDOWN	06/08/83C OK		
8681	B-39	PWR PRESSURE - TEMPERATURE LIMIT TECH SPECS	11/13/80C		
1437	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	05/15/81C OK		
3381	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	03/07/85C OK		
3604	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	11/22/83C OK		
3605	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	11/25/83C OK		
3602	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	05/10/82C OK		
3603	B-41	FIRE PROTECTION - FINAL TECH SPECS (INCLUDES SER S	11/13/81C OK		
1710	B-42	TMI FOLLOW UP - ALL PLANTS	01/30/81C OK		
3130	B-42	TMI FOLLOW UP - ALL PLANTS	07/17/80C OK		
1775	B-43	PWR FEEDWATER LINE CRACKS	09/24/79C		

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
3149	B-43	PWR FEEDWATER LINE CRACKS	05/25/82C		
0736	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0737	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0738	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0739	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0740	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0741	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0742	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0743	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0744	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0745	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0746	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0747	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0748	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
0749	B-44	LESSONS LEARNED IMPLEMENTATION	04/18/80C OK		
2934	B-45	WASH 1400 EVENT V, "PRIMARY COOLANT SYSTEM PRESSUR	04/20/81C OK		
2581	B-46	ANALYSIS OF TURBINE DISC CRACKS	08/19/81C OK		
2685	B-47	ECCS; CLAD SWELLING AND RUPTURE	09/12/80C OK		
2978	B-48	ADEQUACY OF STATION ELECTRIC DISTRIBUTION VOLTAGE	05/07/84C 1/4/84 ?		
1876	B-52	REVIEW OF SAFETY ASPECT OF INADVERTENT SAFETY ACTI	11/26/80C OK		
3234	B-54	LESSONS CATEGORY A TECH SPEC	08/24/81C OK		
2099	B-57	DHR CAPABILITY	03/08/82C OK		
2865	B-59	MASONRY WALL DESIGN	09/23/83C OK		

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

03/31/85

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
2466	B-60	ENVIRONMENTAL QUALIFICATION	03/19/85C	OK	
2704	B-61	LOSS OF NON CLASS IE I&C POWER	07/28/82C		
2775	B-62	ESF RESET CONTROL DESIGN DEFICIENCY	06/12/81C		
3893	B-63	INTERIM PROCEDURES FOR SHORT TERM BLACKOUT	12/17/81C	OK	
7175	B-66	NATURAL CIRCULATION COOLDOWN	09/27/83C	OK	
7548	B-67	THERMAL SHOCK	09/09/82C		
7031	B-67	THERMAL SHOCK	01/21/82C		
6856	B-69	IEB 80-4 MAINSTEAM LINE BREAK WITH CONTINUED FEEDW	01/06/83C		
6635	B-70	FATIGUE TRANSIENT LIMIT TS	05/25/82C		
9753	B-72	NUREG 0737 TECH SPECS (GENERIC LETTER 82-16)	09/12/85C	OK	
9610	B-73	PLANS FOR PREVENTING EXCEEDING PTS SCREENING CRITE	12/05/83C	OK	
2794	B-76	ITEM 1.1 - POST TRIP REVIEW; PROGRAM DESCRIPTION &	05/01/85C	4/1/85?	
2875	B-77	ITEM 2.1 - EQUIPMENT CLASSIFICATION & VENDOR INTER	09/30/86	open	
2956	B-78	ITEMS 3.1.1 & 3.1.2 -POST MAINTENANCE TEST PROCEDU		3/20/86?	
3037	B-79	ITEM 3.1.3 - POST MAINTENANCE TESTING - CHANGES TO	04/30/86	11/18/85?	
3092	B-80	ITEM 4.1 - REACTOR TRIP SYSTEM RELIABILITY - VENDO	01/15/86	3/20/86	
3145	B-81	ITEMS 4.2.1 & 4.2.2 -PREVENTATIVE MAINT PROG FOR R	04/15/86	open	
3191	B-82	ITEM 4.3 - AUTOMATIC ACTUATION OF SHUNT TRIP ATTAC	08/05/85C	OK	
4563	B-83	TECH SPECIFICATIONS COVERED BY GENERIC LETTERS 83-	08/29/85C		
3627	B-85	SALEM ATWS 1.2 DATA CAPABILITY	06/17/85C	OK	
3710	B-86	SALEM ATWS 2.2 S-R COMPONENTS	10/30/86	open	
3793	B-87	SALEM ATWS 3.2.1 & 3.2.2 S-R COMPONENTS	12/31/86	3/20/86?	
3876	B-88	SALEM ATWS 3.2.3 T.S. S-R COMPONENTS	04/30/86	11/18/85?	

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
3932	B-89	SALEM ATWS 4.2.3 & 4.2.4 LIFE COMPONENTS	10/31/86	open	
5373	B-90	SALEM ATWS 4.3 W AND B&W T.S.		? see TAC 54563	
4103	B-92	SALEM ATWS 4.5.1 DIVERSE TRIP FEATURES	11/01/86	3/20/86?	
4020	B-93	SALEM ATWS 4.5.2 & 4.5.3 TEST ALTERNATIVES	04/30/86	open	
8248	C-01	PWR SECONDARY WATER CHEMISTRY MONITORING REQUIREME	12/18/80C	OK	
7695	C-03	QUALIFICATIONS OF RADIATION PROTECTION MANAGER	04/30/79C		
7368	C-06	PUMP SUPPORT-LAMELLAR TEARING	01/01/70C		
3519	C-06	PUMP SUPPORT-LAMELLAR TEARING	04/17/81C		
3080	C-10	CONTROL OF HEAVY LOADS OVER SPENT FUEL POOL (PHASE	05/29/84C	OK	
3636	C-14	AUXILIARY FEEDWATER SEISMIC QUALIFICATION	02/05/85C	OK	
2265	C-15	CONTROL OF HEAVY LOADS - PHASE II (FOLLOWUP OF MPA	06/28/85C	OK	
3083	C-16	UTILITY RESPONSES TO STAFF RECOMMENDATIONS CONCERN	01/02/85C		
8522	D-10	ASYMMETRIC LOCA LOADS	02/01/84C	OK	
8997	D-11	FISSION GAS RELEASE	02/25/80C		
2275	D-15	HIGH ENERGY LINE BREAK & CONSEQUENTIAL SYSTEM FAIL	01/31/84C		
1037	D-17	DEFINITION OF OPERABLE	03/18/82C	OK	
3009	D-17	DEFINITION OF OPERABLE	01/01/70C		
5897	D-19	DIESEL GENERATOR RELIABILITY TECH SPECS (GL 84-15)	10/09/85C	OK	
4053	F-01	I.A.1.1 SHIFT TECHNICAL ADVISOR	01/19/82C	1/15/82?	
4124	F-02	I.A.1.3 SHIFT MANNING	06/30/83C		
4195	F-03	I.A.2.1 UPGRADING OF RO AND SRO TRAINING	04/18/83C	OK	
4266	F-04	I.C.1.2/3.A EMERGENCY OPERATING PROCEDURES GENERIC	06/03/83C	OK	
4336	F-05	I.C.1.2/3.B PROCEDURES GENERATION PACKAGES (NUREG	08/30/86	open	

REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
7249	F-06	I.C.5 FEEDBACK OF OPERATING EXPERIENCE	11/05/81C	OK	
7321	F-07	I.C.6 CORRECT PERFORMANCE OF OPERATING ACTIVITI	11/15/81C	OK	
1197	F-08	I.D.1.1 DETAILED CONTROL ROOM DESIGN REVIEW PROGRA	05/02/85C	open	
1277	F-09	I.D.2 SAFETY PARAMETER DISPLAY SYSTEM	02/28/86	open	
4403	F-10	II.B.1 RCS HIGH POINT VENTS	09/23/83C	OK	
7972	F-11	II.B.2 PLANT SHIELDING	04/18/83C	OK	
4474	F-12	II.B.3 POST ACCIDENT SAMPLING	10/14/85C	OK	
4545	F-13	II.B.4 TRAINING FOR MITIGATING CORE DAMAGE	04/18/83C	OK	
4616	F-14	II.D.1 RV AND SV TRAINING	01/31/86	OK	
4649	F-15	II.E.1.1 AFW SYSTEM EVALUATION	01/06/83C	OK	
4689	F-16	II.E.1.2.1 AFW SYSTEM INITIATION	06/20/84C	ABT STILL OPEN	
4728	F-17	II.E.1.2.2 AFW SYSTEM FLOW INDICATION	06/20/84C	OK	
4813	F-18	II.E.4.1 DEDICATED HYDROGEN PENETRATION	12/14/81C	OK	
4884	F-19	II.E.4.2 CONTAINMENT ISOLATION DEPENDABILITY	02/04/83C	OK	
4955	F-20	II.F.1.1 NOBLE GAS MONITOR	05/18/82C	OK	
5026	F-21	II.F.1.2 IODINE/PARTICULATE SAMPLING	05/18/82C	OK	
5097	F-22	II.F.1.3 CONTAINMENT HIGH RANGE MONITOR	07/26/82C	OK	
7633	F-23	II.F.1.4 CONTAINMENT PRESSURE INSTRUMENT	08/29/85C	OK	
7704	F-24	II.F.1.5 CONTAINMENT WATER LEVEL INSTRUMENT	04/13/84C	OK	
7775	F-25	II.F.1.6 CONTAINMENT HYDROGEN MONITOR	08/29/85C	OK	
5167	F-26	II.F.2 INSTRUMENTS FOR DETECTION ON INADEQUATE	07/30/86	open	
6901	F-30	II.K.2.13 THERMAL-MECHANICAL REPORT	06/18/84C	OK	
7815	F-33	II.K.2.17 POTENTIAL FOR VOIDING IN RCS	09/23/83C	OK	



REGULATORY INFORMATION TRACKING SYSTEM  
FACILITY IMPLEMENTATION

03/31/88

BINSON 2

(CONTINUATION)

C NO.	MPA #	TITLE	LIC ACT COMPLETE	LICENSEE STATUS	DATE
5246	F-36	II.K.3.1 AUTO PORV ISOLATION	09/13/83C	OK	
5292	F-37	II.K.3.2 REPORT ON PORV FAILURES	09/13/83C	OK	
5377	F-38	II.K.3.3 REPORTING SV AND RV FAILURES AND CHALLE	10/20/82C	OK	
5409	F-39	II.K.3.5 AUTO TRIP OF RCPS	02/22/83C	OK	
5458	F-40	II.K.3.9 PID CONTROLLER	12/14/81C	OK	
5488	F-41	II.K.3.10 ANTICIPATORY TRIP MODIFICATIONS	12/14/81C	OK	
5518	F-42	II.K.3.12 ANTICIPATORY TRIP ON TURBINE TRIP	12/14/81C	OK	
5663	F-47	II.K.3.17 ECCS OUTAGES	08/05/83C	OK	
3430	F-53	II.K.3.25 POWER ON PUMP SEALS	10/13/82C	OK	
5860	F-57	II.K.3.30 SB LOCA METHODS	07/10/85C	OK	
8199	F-58	II.K.3.31 COMPLIANCE WITH 10 CFR 50.46	02/15/87	open	
5979	F-63	III.A.1.2 TECHNICAL SUPPORT CENTER	09/30/86	open	
6050	F-64	III.A.1.2 OPERATIONAL SUPPORT CENTER		open	
6122	F-65	III.A.1.2 EMERGENCY OPERATIONS FACILITY	09/30/86	open	
6194	F-66	III.A.1.2 NUCLEAR DATA LINK	07/30/82C		
6266	F-67	III.A.2.1 EMERGENCY PLAN UPGRADE TO MEET RULE	05/11/83C		
6338	F-68	III.A.2.2 METEOROLOGICAL DATA UPGRADE			
6409	F-69	III.D.3.3 IMPLANT RADIATION MONITORING	02/19/82C	OK	
6478	F-70	III.D.3.4 CONTROL ROOM HABITABILITY	07/30/85C	OK	
6159	F-71	I.D.1.2 DETAILED CONTROL ROOM REVIEW (FOLLOWUP TO	09/30/86	open	
9690	G-01	REACTOR COOLANT PUMP TRIP (D660 - II.K.3.5)			