

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 2386

FILE: A/0

FROM: Carolina Power & Light Company Hartsville, S. C. B. J. Furr			DATE OF DOC 3-21-74	DATE REC'D 3-21-74	LTR	MEMO	RPT	OTHER Facsimile
TO: N. C. Moseley			ORIG	CC 1	OTHER	SENT AEC PDR <u>X</u> SENT LOCAL PDR <u>X</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:
Facsimile reporting abnormal occurrence 3-20-74, in which during a routine inspection "B" Boric Acid Transfer Pump was found tripped.....

ENCLOSURES:

DO NOT REMOVE
ACKNOWLEDGED

PLANT NAME: H. B. Robinson #2

FOR ACTION/INFORMATION 3-21-74 GC

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓SCHEMEL(L) W/ 7Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u> ✓AEC PDR ✓GCC, ROOM P-506A ✓MUNTING/STAFF ✓CASE GIAMBUSSO BOYD MOORE (L)(BWR) DEYOUNG(L)(PWR) ✓SKOVHOLT (L) P. COLLINS DENISE ✓ <u>REG OPR</u> FILE & REGION(3) ✓MORRIS ✓STEELE	<u>TECH REVIEW</u> ✓HENDRIE SCHROEDER ✓MACCARY ✓KNIGHT ✓PAWLICKI ✓SHAO ✓STELLO ✓HOUSTON ✓NOVAK ✓ROSS ✓APPOLITO ✓TEDESCO ✓LONG ✓LAINAS ✓BENAROYA ✓VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) LEE (L) MAIGRET (L) SERVICE (L) SHEPPARD (E) SMITH (L) ✓TEETS (L) WADE (E) WILLIAMS (E) WILSON (L) S. REED (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD DUBE w/Input <u>INFO</u> C. MILES ✓B. KING (RO)
--	--	---	---	---

EXTERNAL DISTRIBUTION

✓1 - LOCAL PDR <u>Hartsville, S. C.</u> ✓1 - DTIE(ABERNATHY) ✓1 - NSIC(BUCHANAN) 1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST. ✓16 - CYS ACRS XXXXXX SENT TO LIC. ASST. 3-21-74 TEETS	(1)(2)(10)-NATIONAL LAB'S 1-ASLBP(E/W Bldg, Rm 529) 1-W. PENNINGTON, Rm E-201 GT 1-CONSULTANT'S NEWARK/BLUME/AGBABIAN 1-GERALD ULRICKSON...ORNL	1-PDR-SAN/LA/NY 1-GERALD LELLOUCHE BROOKHAVEN NAT. LAB 1-AGMED(Ruth Gussman) RM-B-127, GT. 1-RD..MULLER..F-309 GT
---	--	--

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

March 21, 1974

50-261

Robinson File No. 2-0-4-a-1

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.

At 1008 hours on March 20, 1974, during a routine inspection, "B" Boric Acid Transfer Pump was found tripped. "A" Boric Acid Transfer Pump was operating at this time, therefore, the system continued to perform its intended function.

This was reported to Mr. Herb Whitener of AEC DRO on March 21, 1974.

Yours very truly,

B. J. Furr
Benny J. Furr, Manager
H. B. Robinson SEG Plant

JEM:GE

2386

