

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8521

FILE:

FROM: Carolina Power & Light Company Hartsville, South Carolina Jack B. McGirt			DATE OF DOC: 8-16-74	DATE REC'D 8-16-74	LTR	TWX	RPT	OTHER Facsimile
TO: Mr. Edison Case			ORIG 1	CC	OTHER	SENT AEC PDR X SENT LOCAL PDR X		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		
	XXXX							

DESCRIPTION:
Facsimile, reporting an Abnormal Occurrence
on 8-15-74, "B" Boric Acid Transfer Pump Tripped.....

ENCLOSURES:

Do Not Remove

PLANT NAME: H. B. Robinson Unit # 2

FOR ACTION/INFORMATION

8-17-74

AB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	LEAR(L) W/ 7 Copies
FARR(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	HENDRIE	GRIMES		BRAITMAN
✓ OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓ PAWLICKI	SPANGLER	KREUTZER (E)	MCDONALD
BOYD	✓ SHAO		LEE (L)	CHAPMAN
MOORE (L)(PWR)	✓ STELLO	<u>ENVIRO</u>	MAIGRET (L)	DUBE w/input
DEYOUNG(L)(PWR)	✓ HOUSTON	MULLER	REED (E)	E. COUPE
SKOVHOLT (L)	✓ NOVAK	DICKER	SERVICE (L)	
✓ COLLER(L)	✓ ROSS	KNIGHTON	SHEPPARD (L)	✓ D. THOMPSON (2)
P. COLLINS	✓ IPPOLITO	YOUNGBLOOD	SLATER (E)	✓ KLECKER
DENISE	✓ TEDESCO	REGAN	SMITH (L)	✓ EISENHUT
REG OPR	✓ LONG	PROJECT LDR	✓ TEETS (L)	
✓ FILE & REGION(2)	✓ LAINAS		WILLIAMS (E)	
✓ MORRIS	✓ BENAROYA	HARLESS	WILSON (L)	
✓ STEELE	✓ VOLLMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Hartville, SC.	(1) (2X10)-NATIONAL LAB'S	1-PDR-SAN/LA/NE
✓ 1 - TIC (ABERNATHY)		1-LIBRARIAN
✓ 1 - NSIC(BUCHANAN)		BROOKHAVEN NAT. LAB
1 - ASLB(LANDOW BLDG)	1-W. PENNINGTON, Rm E-201 GT	1-AGMED(Ruth Cussman)
1 - Newton Anderson(AEROJET NUCLEAR)	1-CONSULTANT'S	RM-E-127, GT.
✓ 5 - CYS ACRS XXXXXXXX SENT TO LIC ASST.	NEWMARK/BLUME/ACBARIAN	1-RD..MULLER..F-305
S. TEETS FOR DIST.	1-GERALD ULRIKSON...ORNL	
	1-B & M SWINEBROAD, Rm E-201 GT	

Regulatory

File Cy

CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

August 16, 1974

Robinson File No. 2-O-4-a-1

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Mr. Edison Case, Acting Director
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.


At 1825 hours on August 15, 1974, during a routine periodic test, "B" Boric Acid Transfer Pump tripped. "A" Boric Acid Transfer Pump was tested satisfactorily at this time; therefore, the system continued to perform its intended function. Investigation revealed that the pump shaft was broken. A spare pump was installed, and the system was returned to normal at 2304, August 15, 1974.

This was reported to Mr. Herb Whitener of ABE DRG on August 16, 1974.

Yours very truly,

J B McGirt
Jack B. McGirt, Manager
H. B. Robinson BEP Plant

ACT:ES



8521