

50-261

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr. Norman C. Moseley

FROM: Carolina Power & Light Co
~~RXX~~ Raleigh, N.C.
H.R. Banks

DATE OF DOCUMENT

7/21/77

DATE RECEIVED

7-22-77

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1cc

DESCRIPTION

Ltr trans the following: 1P

ENCLOSURE

Licensee event rept #77-12
concerning union pump company pump, type
TX-150 became air bound due to accumulation
of air at suction of the pump..... with
attached suppl ~~xxx~~ info to RO-77-12....

(1 cy encl rec'd) 3P

PLANT NAME: H. B. Robinson

DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

DHL 7-25-77

FOR ACTION/INFORMATION

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC. ASST.:

W/ CYS

ACRS 16 CYS /SENT AS CAT B

Reid (4)

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNGH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Hartsville, SC

TIC:

NSIC:

CONTROL NUMBER

772060055