



CONNECTICUT YANKEE ATOMIC POWER COMPANY

TELEPHONE
203-666-6911

BERLIN, CONNECTICUT

P. O. BOX 270 HARTFORD, CONNECTICUT 06101

August 14, 1980

Docket No. 50-213
A01144

Mr. M. R. Beebe
Licensee Operations Evaluation Branch
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Reference: (1) R. A. Hartfield letter to D. C. Switzer dated July 18, 1980.

Dear Mr. Beebe:

Haddam Neck Plant
Summary of Radioactive Effluents

In Reference (1), the NRC Staff requested Connecticut Yankee Atomic Power Company (CYAPCO) to verify information on radioactive effluents for the Haddam Neck Plant. It is noted that a similar request was not received by Northeast Nuclear Energy Company (NNECO) regarding Millstone Unit Nos. 1 and 2. The following discrepancies in the Haddam Neck Plant information have been identified.

(1) Maximum Permissible Concentrations:

Xe 138 should be 3×10^{-8}

(2) Batch Release Summary - Liquids:

Item A.6 - should be 1.58×10^4 Ft³/sec

CYAPCO is not familiar with the units of "LTS/minute"

(3) All Gaseous and Liquid Summary Tables:

All M Ci/sec or M Ci/mL should be uCi/sec or uCi/mL

A007
5/0

8008260484

(4) Solid Waste - July - December, 1978

Add: 3. Solid Waste Disposition

<u># Shipments</u>	<u>Mode</u>	<u>Destination</u>
5	Truck	Barnwell, SC


B. Irradiated Fuel Shipments - None

Additionally, all further correspondence should be addressed to Mr. W. G. Counsil, Senior Vice President, CYAPCO.

We trust these corrections and additions will be incorporated into your final report.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY



W. G. Counsil
Senior Vice President



W. F. Fee
Executive Vice President