



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**  
REGION I  
2100 RENAISSANCE BLVD., SUITE 100  
KING OF PRUSSIA, PA 19406-2713

September 2, 2014

Mr. Eric A. Larson, Site Vice President  
FirstEnergy Nuclear Operating Company  
Beaver Valley Power Station  
P. O. Box 4, Route 168  
Shippingport, PA 15077

**SUBJECT: MID-CYCLE ASSESSMENT LETTER FOR BEAVER VALLEY POWER  
STATION, UNIT NOS. 1 AND 2 (REPORT 05000334/2014006 AND  
05000412/2014006)**

Dear Mr. Larson:

On August 13, 2014, the U.S. Nuclear Regulatory Commission (NRC) completed its mid-cycle performance review of Beaver Valley Power Station, Unit Nos. 1 and 2. The NRC reviewed the most recent quarterly performance indicators in addition to inspection results and enforcement actions from July 1, 2013 through June 30, 2014. This letter informs you of the NRC's assessment of your facility during this period and its plans for future inspections at your facility.

The NRC determined that overall, Beaver Valley Power Station, Unit Nos. 1 and 2 were operated in a manner that preserved public health and safety and met all cornerstone objectives. The NRC determined the performance at Beaver Valley Power Station Unit Nos. 1 and 2 during the most recent quarter was within the Licensee Response Column of the NRC's Reactor Oversight Process Action Matrix because all inspection findings had very low (i.e., green) safety significance, and all performance indicators demonstrated that your performance was within the nominal, expected range (i.e., green). Therefore, the NRC plans to conduct Reactor Oversight Process baseline inspections at your facility.

The enclosed inspection plan lists the inspections scheduled through December 31, 2015. Routine inspections performed by resident inspectors are not included in the inspection plan. The inspections listed during the last nine months of the inspection plan are tentative and may be revised at the end-of-cycle performance review. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes. This inspection plan does not include security related inspections, which will be sent via separate, non-publicly available correspondence. In addition to baseline inspections, the NRC will perform Inspection Procedure (IP) 60854.1, "Preoperational Testing of ISFSI at Operating Plants," IP 60856.1, "Review of 10CFR72.212(b) Evaluation at Operating Plants," IP 60855.1, "Operation of an ISFSI at Operating Plants," and IP 71003, "Post Approval Site Inspection For License Renewal."

In response to the accident at Fukushima, the Commission issued Order EA-12-049, "Order Modifying Licenses with Regard to Requirements for Mitigation Strategies for Beyond-Design-Basis External Events," which requires licensees to develop, implement, and maintain guidance

and strategies to maintain or restore core cooling, containment, and spent fuel pool cooling capabilities following a beyond-design-basis external event. Additionally, the Commission issued Order EA-12-051, "Order Modifying Licenses with Regard to Reliable Spent Fuel Pool Instrumentation," which requires licensees to have a reliable means of remotely monitoring wide-range Spent Fuel Pool levels to support effective prioritization of event mitigation and recovery actions in the event of a beyond-design-basis external event. The NRC is conducting audits of licensee efforts towards compliance with these Orders. This audit includes an onsite component in order for the NRC to evaluate licensee plans for complying with the Orders, as described in site-specific submittals, and to receive and review information relative to associated open items. This onsite activity will occur in the months prior to a declaration of compliance for the first unit at each site, and will aid staff in development of an ultimate Safety Evaluation for the site. The date for the onsite component at your site is being coordinated with your staff. A site-specific audit plan for the visit will be provided in advance to allow sufficient time for preparations.

As a result of the Safety Culture Common Language Initiative, the terminology and coding of cross-cutting aspects were revised. All cross-cutting aspects identified during inspections conducted in calendar year 2014 will reflect this revision to Inspection Manual Chapter (IMC) 0310. During the 2014 mid-cycle assessment review, cross-cutting aspects identified in 2013 using the 2013 terminology were converted to the latest revision in accordance with the cross-reference in IMC 0310, and were evaluated for cross-cutting themes and potential substantive cross-cutting issues in accordance with IMC 0305.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR), Part 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of the NRC's Agencywide Document Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at (610)337-5046 with any questions you have regarding this letter.

Sincerely,

/RA/

Silas R. Kennedy, Chief  
Projects Branch 6  
Division of Reactor Projects

Docket Nos.: 50-334, 50-412  
License Nos.: DPR-66, NPF-73

Enclosure: Inspection Plan

cc w/encl: Distribution via ListServ

and strategies to maintain or restore core cooling, containment, and spent fuel pool cooling capabilities following a beyond-design-basis external event. Additionally, the Commission issued Order EA-12-051, "Order Modifying Licenses with Regard to Reliable Spent Fuel Pool Instrumentation," which requires licensees to have a reliable means of remotely monitoring wide-range Spent Fuel Pool levels to support effective prioritization of event mitigation and recovery actions in the event of a beyond-design-basis external event. The NRC is conducting audits of licensee efforts towards compliance with these Orders. This audit includes an onsite component in order for the NRC to evaluate licensee plans for complying with the Orders, as described in site-specific submittals, and to receive and review information relative to associated open items. This onsite activity will occur in the months prior to a declaration of compliance for the first unit at each site, and will aid staff in development of an ultimate Safety Evaluation for the site. The date for the onsite component at your site is being coordinated with your staff. A site-specific audit plan for the visit will be provided in advance to allow sufficient time for preparations.

As a result of the Safety Culture Common Language Initiative, the terminology and coding of cross-cutting aspects were revised. All cross-cutting aspects identified during inspections conducted in calendar year 2014 will reflect this revision to Inspection Manual Chapter (IMC) 0310. During the 2014 mid-cycle assessment review, cross-cutting aspects identified in 2013 using the 2013 terminology were converted to the latest revision in accordance with the cross-reference in IMC 0310, and were evaluated for cross-cutting themes and potential substantive cross-cutting issues in accordance with IMC 0305.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR), Part 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of the NRC's Agencywide Document Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at (610)337-5046 with any questions you have regarding this letter.

Sincerely,

/RA/

Silas R. Kennedy, Chief  
Projects Branch 6  
Division of Reactor Projects

Docket Nos.: 50-334, 50-412  
License Nos.: DPR-66, NPF-73

Enclosure: Inspection Plan

cc w/encl: Distribution via ListServ

Distribution: See next page

DOC NAME: S:\ROP ASSESSMENT MEETINGS\ROP-15 MID-CYCLE REVIEW\BRANCH 6\BEAVER VALLEY\2014 BEAVER VALLEY MC LETTER FINAL.DOCX  
ADAMS Accession No.: **ML14239A214**

<input checked="" type="checkbox"/> SUNSI Review		<input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Sensitive		<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available	
OFFICE	RI/DRP	RI/DRP	RI/DRP		
NAME	JKrafty/ LC for	LCline/ LC	SKennedy/ SRK		
DATE	08/26/14	08/26/14	08/27/14		

OFFICIAL RECORD COPY

Distribution w/encl:

W. Dean, RA  
D. Lew, DRA  
H. Nieh, DRP  
M. Scott, DRP  
J. Trapp, DRS  
B. Welling, DRS  
S. Kennedy, DRP  
L. Cline, Acting, DRP  
C. Roettgen, DRP  
B. Bollinger, DRP  
J. Krafty, DRP, SRI  
E. Andrews, DRP, Actg RI  
P. Garrett, DRP, Resident AA  
A. Bowers, RI OEDO  
R. Powell, DRP  
DRS Branch Chiefs (6)  
N. McNamara, RI, SLO  
D. Tifft, RI, SLO  
D. Screnci, RI, PAO  
N. Sheehan, RI, PAO  
RidsNrrDirslpabResource  
ROPassessment Resource  
RidsNrrPMBeaverValley Resource  
RidsNrrDorlLp1-2 Resource  
ROPreports Resource

**Beaver Valley**  
**Inspection / Activity Plan**  
**07/01/2014 - 12/31/2015**

Unit Number	Planned Dates Start End	Inspection Activity	Title	No. of Staff on Site
		<b>7/7EXAM - U1 INITIAL OL EXAM</b>		<b>4</b>
1	07/07/2014 07/16/2014	U01884	FY14 -BEAVER VALLEY 1 INITIAL OPERATOR LICENSING EXAM	
		<b>7111111B - U1 REQUAL INSPECTION WITH P/F RESULTS</b>		<b>2</b>
1	09/01/2014 09/05/2014	IP 7111111B	Licensed Operator Requalification Program	
		<b>ISFSI - DRY RUN &amp; INITIAL ISFSI INSPECTION</b>		<b>3</b>
1, 2	09/01/2014 09/19/2014	IP 60854	Preoperational Testing Of An ISFSI	
1	09/01/2014 09/19/2014	IP 60854.1	Preoperational Testing of Independent Spent Fuel Storage Facility Installation at Operating Plants	
1, 2	09/01/2014 09/19/2014	IP 60855	Operation Of An ISFSI	
1, 2	09/01/2014 09/19/2014	IP 60856	Review of 10 CFR 72.212(b) Evaluations	
2	09/01/2014 09/19/2014	IP 60856.1	Review of 10 CFR 72.212(b) Evaluations at Operating Plants	
1	09/22/2014 09/26/2014	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
		<b>CDBI - CDBI</b>		<b>6</b>
1, 2	11/03/2014 11/07/2014	IP 7111121	Component Design Bases Inspection	
1, 2	11/17/2014 11/21/2014	IP 7111121	Component Design Bases Inspection	
1, 2	12/01/2014 12/05/2014	IP 7111121	Component Design Bases Inspection	
		<b>71124.08 - RADWASTE</b>		<b>1</b>
1, 2	11/17/2014 11/21/2014	IP 71124.08	Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	
		<b>71124 - OCC RADIATION SAFETY</b>		<b>1</b>
1, 2	12/15/2014 12/19/2014	IP 71124.06	Radioactive Gaseous and Liquid Effluent Treatment	
1, 2	12/15/2014 12/19/2014	IP 71151	Performance Indicator Verification	
		<b>EP - EP PROGRAM INSPECTION</b>		<b>1</b>
1, 2	01/01/2015 07/02/2015	IP 7111404	Emergency Action Level and Emergency Plan Changes	
1, 2	06/29/2015 07/02/2015	IP 7111402	Alert and Notification System Testing	
1, 2	06/29/2015 07/02/2015	IP 7111403	Emergency Preparedness Organization Staffing and Augmentation System	
1, 2	06/29/2015 07/02/2015	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies	
		<b>71124 - RAD SAFETY INSPECTION</b>		<b>1</b>
1, 2	04/20/2015 04/24/2015	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1, 2	04/20/2015 04/24/2015	IP 71124.02	Occupational ALARA Planning and Controls	
1, 2	04/20/2015 04/24/2015	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1, 2	04/20/2015 04/24/2015	IP 71124.04	Occupational Dose Assessment	
		<b>7111108P - U1 INSERVICE INSPECTION</b>		<b>1</b>
1	05/04/2015 05/15/2015	IP 7111108P	Inservice Inspection Activities - PWR	
		<b>71003 - LR COMMITMENTS PHASE I OUTAGE INSP</b>		<b>2</b>
1	05/11/2015 05/15/2015	IP 71003	Post-Approval Site Inspection for License Renewal	

This report does not include INPO and OUTAGE activities.  
This report shows only on-site and announced inspection procedures.

**Beaver Valley**  
**Inspection / Activity Plan**  
**07/01/2014 - 12/31/2015**

Unit Number	Planned Dates Start End	Inspection Activity	Title	No. of Staff on Site
		<b>711111B - U2 REQUAL INSP W/ P/F RESULTS</b>		<b>2</b>
2	08/24/2015 08/28/2015	IP 711111B	Licensed Operator Requalification Program	
		<b>71124.07 - RAD SAFETY INSPECTION</b>		<b>1</b>
1,2	07/06/2015 07/10/2015	IP 71124.07	Radiological Environmental Monitoring Program	
1,2	07/06/2015 07/10/2015	IP 71151	Performance Indicator Verification	
		<b>TRI FI - TRIENNIAL FIRE PROTECTION INSPECTION</b>		<b>4</b>
1,2	08/03/2015 08/07/2015	IP 7111105T	Fire Protection [Triennial]	
1,2	08/17/2015 08/21/2015	IP 7111105T	Fire Protection [Triennial]	
		<b>12/7EXAM - U2 INITIAL OL EXAM</b>		<b>4</b>
2	11/09/2015 11/13/2015	U01906	FY16-BV2 INITIAL OPERATOR LICENSING EXAM	
2	12/07/2015 12/18/2015	U01906	FY16-BV2 INITIAL OPERATOR LICENSING EXAM	
		<b>71003 - LR COMMITMENTS PHASE II TEAM INSP</b>		<b>4</b>
1	08/31/2015 09/04/2015	IP 71003	Post-Approval Site Inspection for License Renewal	
1	09/14/2015 09/18/2015	IP 71003	Post-Approval Site Inspection for License Renewal	
		<b>PI&amp;R - PI&amp;R BIENNIAL</b>		<b>4</b>
1,2	10/05/2015 10/09/2015	IP 71152B	Problem Identification and Resolution	
1,2	10/19/2015 10/23/2015	IP 71152B	Problem Identification and Resolution	
		<b>7111108P - U2 INSERVICE INSPECTION</b>		<b>1</b>
2	10/05/2015 10/16/2015	IP 7111108P	Inservice Inspection Activities - PWR	
		<b>71124 - RAD SAFETY INSP</b>		<b>1</b>
1,2	10/19/2015 10/23/2015	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1,2	10/19/2015 10/23/2015	IP 71124.02	Occupational ALARA Planning and Controls	
1,2	10/19/2015 10/23/2015	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1,2	10/19/2015 10/23/2015	IP 71124.04	Occupational Dose Assessment	
1,2	10/19/2015 10/23/2015	IP 71124.05	Radiation Monitoring Instrumentation	
		<b>71124 - RAD SAFETY INSP</b>		<b>1</b>
1,2	12/14/2015 12/18/2015	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1,2	12/14/2015 12/18/2015	IP 71124.02	Occupational ALARA Planning and Controls	
1,2	12/14/2015 12/18/2015	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1,2	12/14/2015 12/18/2015	IP 71124.04	Occupational Dose Assessment	
1,2	12/14/2015 12/18/2015	IP 71151	Performance Indicator Verification	

This report does not include INPO and OUTAGE activities.  
This report shows only on-site and announced inspection procedures.