

**From:** Travis Coleman <Travis\_Coleman@cameco.com>  
**Sent:** Tuesday, September 09, 2014 9:55 AM  
**To:** Mandeville, Douglas; miles.bennett@wyo.gov; joe.hunter@wyo.gov; luke.mcmahan@wyo.gov  
**Cc:** Tyler Schiltz; Kenneth Garoutte  
**Subject:** Reportable Spill, North Butte Mine Unit #1, WDEQ Permit 632, NRC Source Material Licence SUA-1548

All,

This email is to document that verbal notification or voice mail was given to your office on 9-9-14 of a reportable release on Permit 632, NRC Source Material License SUA-1548. The release happened on Monday, 9/8/14 at approximately 0700 am. The data reported was as follows;

- Location: Wellfield #1, near Header House #9, injection well I-201.
- Fluid release estimated at 187 gallons of injection fluid onto the ground surface. Fluid entered dry draw considered Waters of the State. A sample for uranium content showed 2.71 ppm.
- Cause: Failed Pop-off, along with settling on the ground allowing well basin to settle in an uneven manner with the leak detection on the high side allowing fluid to spill over well basin until water reached a depth to trip the leak detection device, shutting the well down.

The WDEQ-Emergency Response Coordinator (Joe Hunter) and WDEQ- Uranium Coordinator Miles Bennett were given verbal notification.

A written notification will be sent out on or before Friday September 12, 2014.

Thank you,

Travis Coleman  
North Butte  
Cameco Resources  
213 N. Uranium Rd  
Gillette Wy, 82718  
307-622-1247 office  
[travis\\_coleman@cameco.com](mailto:travis_coleman@cameco.com)

This email and any files transmitted with it are personal and confidential, and are solely for the use of the individual or entity addressed. Therefore, if you are not the intended recipient, please delete this email and any files transmitted with it (without making any copies) and advise the author immediately.