



April 17, 2015

NRC:15:017

U.S. Nuclear Regulatory Commission
Document Control Desk
11555 Rockville Pike
Rockville, MD 20852

Notification of Errata to Technical Report BAW-1902, "RELAP5/MOD2 Benchmark of OTIS Leak Size Test #2202A"

AREVA Inc. (AREVA) identified an error in the licensing technical report BAW-1902, "RELAP5/MOD2 Benchmark of OTIS Leak Size Test #2202AA." This technical report was not formally transmitted to the NRC by AREVA, but may have been transmitted by approved users of the document.

BAW-1902 is referenced in at least two NUREG Publications. The two publications are:

1. NUREG-1230 Rev. 4 Compendium of ECCS Research for Realistic LOCA Analysis (Final Report)
2. NUREG/CR-5535 Vol. 5 RELAP5/MOD3 Code Manual


Please note that the subject document is referenced in the above NUREGs as BAW-1092 instead of the correct reference of BAW-1902.

The enclosure to this letter provides the errata, which includes the title page, three replacement pages, and one additional page (Record of Revisions) for the subject Technical Report. The errors identified are considered to be typographical in nature. This letter will serve as notification to the NRC of the corrections to these errors. The errors and changes identified in the Record of Revisions do not affect any conclusions made within the technical report.

AREVA does not consider any of the material contained in the attachment to be proprietary.

If you have any questions related to this information, please contact Mr. Morris Byram, Licensing Manager by telephone at 434-832-4665, or by e-mail at Morris.Byram@areva.com.

Sincerely,



Pedro Salas, Director
Licensing & Regulatory Affairs
AREVA Inc.

cc: J.G. Rowley
Project 728

AREVA INC.

3315 Old Forest Road, Lynchburg, VA 24501
Tel.: 434 832 3000 - www.areva.com

TOIO
NRR