

CBR Violations, Spills, and Leaks as of July 28, 2008

Prepared by Shane Robinson on behalf of Western Nebraska Resources Council

- June 19, 2008: Power outage resulting in loss of flow to the well field and exceedance of the 100 PSIG NDEQ Class III UIC permit limitation.
- June 4, 2008: Exceeding of Well Head Manifold Pressure Limitations
- May 15, 2008: CM9-5 Monitor Well Excursion
- May 30, 2008: CM9-3 Monitor Well Excursion
- April 29, 2008: Thirty day response to self identified license violation for missed five-year MIT re-tests
- January 24, 2007: 2006 Annual pond inspection report is 45 days past due and has been recorded as a self identified reporting violation
- September 26, 2006: Monitor well placed on excursion status
- May 5, 2006: Evaporation Pond 4 Liner Leak
- March 31, 2006: CBR became aware of the noncompliance of three violations listed below on July 1, 2003 and failed to provide written notification to NDEQ as required by Title 122, Chapter 21 §001.06 until May 12, 2006.
- January 18, 2006: CM8-21 Monitor Well Excursion
- October 27, 2005: 5-Year Mechanical integrity test failure at well 12340-31 leak detected
- August 4, 2005: CM9-16 Monitor Well Excursion
- July 4, 2005: Mechanical integrity test failure at well 1723-14
- June 27, 2005: SM6-12 Monitor Well Excursion
- May 2, 2005: CM5-19 Monitor Well Excursion
- June 16, 2005: SM6-28 Monitor Well Excursion
- May 14, 2004: leak detected at Pond 1
- December 23, 2003: Monitor well placed on excursion status
- July 1, 2003: Violations of Permit by releasing well development water upon the surface of the ground (**continued until March, 31, 2006**)
- July 1, 2003: Violation of Permit by using Chadron Formation well development water as drilling water (**continued until March, 31, 2006**)
- July 1, 2003: constructed injection wells and mineral production wells in a manner that had the potential to allow the movement of fluid containing contaminants into an underground source of drinking water, in violation of Title 122, Chapter 4, §001 (**continued until March, 31, 2006**)
- December 26, 2002: Monitor well placed on excursion status
- September 10, 2002: Monitor well placed on excursion status
- April 4, 2002: Monitor well placed on excursion status
- December 4, 2001: Monitor well placed on excursion status
- March 2, 2001: Monitor well placed on excursion status
- September 10, 2000: Monitor well placed on excursion status
- May 26, 2000: Monitor well placed on excursion status
- April 27, 2000: Monitor well placed on excursion status
- March 6, 2000: Monitor well placed on excursion status
- July 2, 1999: Monitor well placed on excursion status
- August 7, 1998: Spill of 10,260 gallons of injection fluid
- March 21, 1998: Monitor well placed on excursion status