

## List of Changed SAR Pages with Reason for Change

Page #	Reason for Change
SAR Pages	
2-32, 2-33	Revise internal pressure load and seismic load to reflect analyses documented in Appendix 3.9.1
3.9.1-i through 3.9.1-iv	Editorial to update Table of Contents, List of Tables and List of Figures
3.9.1-2	Update Cross-Reference and response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-4 through 3.9.1-6	Response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-7	Response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-8 through 3.9.1-11	Response to Issue 1 identified in Reference 2 of the cover letter
3.9.1-12	Section numbering changes
3.9.1-13	Add reference to Figure 3.9.1-7a since it is now a separate figure (former Figure 3.9.1-7 had 2 graphics embedded – now split into 2 figures)
3.9.1-14	Section numbering changes
3.9.1-15 through 3.9.1-26	Response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter, and section numbering changes
3.9.1-29 and 3.9.1-30	Response to Issues 1, 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-31, 3.9.1-33, and 3.9.1-35 through 3.9.1-55	Response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-56	Response to Issue 1 identified in Reference 2 of the cover letter
3.9.1-57 through 3.9.1-86	Response to Issues 2, 3, and 4 identified in Reference 2 of the cover letter
3.9.1-87 through 3.9.1-89	Response to Issue 1 identified in Reference 2 of the cover letter