

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

United Hospital Center
327 Medical Park Drive
Bridgeport, West Virginia 26330

REPORT NUMBER(S)

2015001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 2100 Renaissance Blvd, Suite 100
King of Prussia, Pennsylvania 19406-2713

3. DOCKET NUMBER(S)

030-03375

4. LICENSE NUMBER(S)

47-01458-01

5. DATE(S) OF INSPECTION

June 8-9, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)




10 CFR 71.5(a) requires, in part, that each licensee who delivers licensed material to a carrier for transport, shall comply with the applicable requirements of the DOT regulations in 49 CFR parts 171 through 180, appropriate to the mode of transport.

49 CFR 172.702(b) requires, in part, except as provided in 172.704(c)(1), a hazmat employee who performs any function subject to the requirements of this subchapter may not perform that function unless instructed in the requirements of this subchapter that apply to that function. Contrary to the above, United Hospital Center did not provide, as of June 9, 2015, training to HAZMAT employees to comply with the applicable requirements of the DOT regulations in 49 CFR parts 171 through 180. Specifically, nuclear medicine technologists had not received HAZMAT training. This is a Severity Level II violation.

Statement of Corrective Actions

Licensee to provide HAZMAT training to Nuclear Medicine staff within 30 days.

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	JOHN FERNANDEZ		6/9/15
NRC INSPECTOR	Janice Nguyen/John Nicholson		6-9-15
BRANCH CHIEF	James Dwyer		7/6/15

SUNSI Review Completed By: / RA / John Nicholson

☒

Public

☒

Non-Sensitive