

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Rink International, LLC
1277 Gold Hill Road
Princeton, Idaho 83857

REPORT NO: 030-36268/2015-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-36268

4. LICENSE NUMBER

11-27756-01

5. DATE OF INSPECTION

June 19, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



1. Based on the inspection findings, no violations were identified.



2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.






Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTORS	Rick Muñoz Jason Dykert	 	6/30/2015 7/1/15
BRANCH CHIEF	G.M. Vasquez		8/5/2015



Non-Public



Sensitive – Security-Related



Public



Non-Sensitive

Dykert, Jason

From: Dykert, Jason
Sent: Thursday, July 02, 2015 2:18 PM
To: 'rinkint@aol.com'
Cc: Munoz, Rick
Subject: Inspection report 2015-001
Attachments: Rink 591.pdf

Dr. Rink, please find the attached inspection report for your records.

We appreciate your availability for the inspection and forthcoming answers regarding applications using the Radiflo.

If we can be of assistance in amending your license or with any other regulatory/inspection issues please give us a call.

Jason C Dykert
Health Physicist, Inspection Branch
US NRC, Region IV
(817) 200 - 1427

