

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7812190153 DOC. DATE: 78/12/08 NOTARIZED: NO

DOCKET #
05000287

FACIL: 50-287 OCONEE #3, DUKE POWER CO.

AUTH. NAME AUTHOR AFFILIATION

PARKER, W.O. DUKE POWER CO.

RECIP. NAME RECIPIENT AFFILIATION

O'REILLY, J.P. **REG. 2, ATLANTA, OFF. OF THE DIRECTOR

7-31-78
 SUBJECT: Forwards LER#78-015/03L-0. RPS Channel A, RC flow indication began reading high on 780729 & was valved out-of-svc on 780731 caused by leak in pressure transmitter impulse line. Leaking fittings were repaired.

DISTRIBUTION CODE: A002S. COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2

TITLE: INCIDENT REPORTS

NOTES: M CUNNINGHAM - ALL AMDTS TO FSAR + CHANGES TO TECH SPECS

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC ORB #4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 HANAUER	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

DEC 20 1978

DEC 20 1978

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 43

ccp

A01-4

REGULATORY DOCKET FILE COPY
DUKE POWER COMPANY
POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 8, 1978

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 3
Docket No. 50-287

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Reportable Occurrence
Report RO-287/78-15.

Very truly yours,



William O. Parker, Jr.

KRW:ldh

Attachment

812190153

A002
S11
5