

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8102230667 DOC.DATE: 81/02/17 NOTARIZED: NO  
 FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH.NAME: JONES, J.L. AUTHOR AFFILIATION: Duke Power Co.  
 RECIP.NAME: REGION 2, Atlanta, Office of the Director

DOCKET #  
 05000269

SUBJECT: LER 81-002/03L-0: on 810118, DC input fuse in 1DID vital inverter blew during power reduction. Possibly caused by poorly made connections in logic cards edge connectors &/or intermitten component problems on logic cards.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2  
 TITLE: Incident Reports

NOTES: M Cunningham: all amends to FSAR & changes to Tech Specs. 05000269  
 AEOD, Ornstein: lcc.

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME	LTTR
INTERNAL:	AEOD	04	3	3	AEOD	3	3
	AUX SYS BR	15	1	1	AUX SYS BR	1	1
	CONT SYS BR	17	1	1	CONT SYS BR	1	1
	DIR, DIV OF LIC		1	1	DIR, DIV OF LIC	1	1
	DIR, HUM FAC	S21	1	1	DIR, HUM FAC	1	1
	EFF TR SYS BR	23	1	1	EFF TR SYS BR	1	1
	GEOSCIENCES	26	1	1	GEOSCIENCES	1	1
	I&E	05	2	2	I&E	1	1
	LIC GUID BR	30	1	1	LIC GUID BR	1	1
	MECH ENG BR	33	1	1	MECH ENG BR	3	3
	NRC PDR	02	1	1	NRC PDR	3	3
	OR ASSESS BR	35	1	1	OR ASSESS BR	1	1
	RAD ASSESS BR	39	1	1	RAD ASSESS BR	1	1
	REG FILE	01	1	1	REG FILE	1	1
	SFTY PROG EVA	42	1	1	SFTY PROG EVA	1	1
	SYS INTERAC	B45	1	1	SYS INTERAC	1	1
EXTERNAL:	ACRS	46	16	16	ACRS	1	1
	NSIC	05	1	1	NSIC	1	1
	LPDR	03	1	1	LPDR	1	1
	TERA: DOUG MAY		1	1	TERA: DOUG MAY	1	1

FEB 25 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 69 ENCL 69