

Ential file

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 20, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JP0
50-269 -270. -287
I.E. Bulletin 81-01



Dear Sir:

Your letter dated January 27, 1981, which transmitted I.E. Bulletin 81-01, requested a response concerning the surveillance of mechanical snubbers. Since Oconee Nuclear Station has none of the INC snubbers identified in the bulletin, items 1 and 2 of the subject bulletin do not apply. In response to your request concerning item 3, Duke Power completed a full inspection of the Unit 3 inaccessible mechanical snubbers on February 20, 1981, per bulletin requirements. Everything was clean. The Unit 1 and Unit 2 inaccessible mechanical snubbers will be done during the next refueling outage for each unit. The inspection of Unit 1, Unit 2, and Unit 3 accessible mechanical snubbers will be completed by May 31, 1981.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge, executed on March 20, 1981.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

JLJ:pw

cc: Director
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8103310913

Q