

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8805020065 DOC. DATE: 88/04/22 NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH. NAME TUCKER, H. B. AUTHOR AFFILIATION Duke Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

DOCKET #  
 05000269

SUBJECT: Advises that LER 269/88-04 submitted by 880406 ltr re  
 emergency power switching logic retransfer to startup logic  
 will be revised. Util now evaluating new info re incident.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: AEOD/Ornstein:1cy.

05000269

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 LA	1		PD2-3 PD	1
	PASTIS, H	1			
INTERNAL:	ACRS MICHELSON	1		ACRS MOELLER	2 2
	AEOD/DOA	1		AEOD/DSP/NAS	1
	AEOD/DSP/ROAB	2 2		AEOD/DSP/TPAB	1
	ARM/DCTS/DAB	1 1		DEDRO	1
	NRR/DEST/ADS 7E	1 0		NRR/DEST/CEB 8H	1
	NRR/DEST/ESB 8D	1		NRR/DEST/ICSB 7	1
	NRR/DEST/MEB 9H	1		NRR/DEST/MTB 9H	1
	NRR/DEST/PSB 8D	1 1		NRR/DEST/RSB 8E	1
	NRR/DEST/SGB 8D	1 1		NRR/DLPQ/HFB 10	1
	NRR/DLPQ/QAB 10	1 1		NRR/DOEA/EAB 11	1
	NRR/DREP/RAB 10	1 1		NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1		NRR/PMAS/ILRB12	1 1
	<u>REG FILE</u> 02	1		RES TELFORD, J	1 1
	RES/DE/EIB	1		RES/DRPS DIR	1 1
	RGN2 FILE 01	1			
EXTERNAL:	EG&G GROH, M	4 4		FORD BLDG HOY, A	1
	H ST LOBBY WARD	1		LPDR	1
	NRC PDR	1		NSIC HARRIS, J	1
	NSIC MAYS, G	1 1			
NOTES:		1 1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 0

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

April 22, 1988


U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
LER 269/88-04

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), Licensee Event Report (LER) 269/88-04 was submitted to your office by letter dated April 6, 1988. LER 269/88-04 concerned Emergency Power Switching Logic retransfer to startup logic. Duke is evaluating new information regarding this incident and will revise the LER as necessary.

Very truly yours,



Hal B. Tucker

PJN/2/sbn

xc: Dr. J. Nelson Grace  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Ms. Helen Pastis  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, New York 10020

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

Mr. P. H. Skinner  
NRC Resident Inspector  
Oconee Nuclear Station

8805020065 880422  
PDR ADDCK 05000269  
S PDR

IER 2  
10