

DUKE POWER COMPANY
USNR REGION II
ATLANTA BUILDING
ATLANTA, GEORGIA

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

81 JUL 9 09:12

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 6, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:GAB
50-269/81-06
50-270/81-06
50-287/81-06

Dear Mr. O'Reilly:

Mr. A. C. Thies' letter of May 22, 1981, transmitted the responses to the cited items of noncompliance of the subject inspection report. The following supplements the responses for Violations C and E.

Violation C Supplement


A policy has been established by the Quality Assurance Department to preclude the recurrence of the condition that resulted in the referenced violation. If a response to an audit item is determined to be unacceptable, the matter will be brought to the attention of successive management levels in order that item may be acceptably closed out. Details of this policy are available from the Quality Assurance Department.

Violation E Supplement

Approximately 10,000 file inches of vault condition storage are required to meet present needs at the Oconee Nuclear Station. Reracking the vault with high density racks will provide 10,000 file inches of storage. Approximately 3,000 to 4,000 file inches of old Quality Assurance records will be transferred to the Cherokee vault, thus leaving 3,000 to 4,000 file inches for growth. Based on this, a new vault for Oconee Nuclear Station will be deferred until a later date.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge, executed on July 1, 1981.

Very truly yours,


William O. Parker, Jr.

JLJ:pw

8109010509 810814
PDR ADDCK 05000269
Q PDR