

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8003200449 DOC. DATE: 80/03/17 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: DENTON, H.R. RECIPIENT AFFILIATION: Office of Nuclear Reactor Regulation
 REID, R.W. Operating Reactors Branch 4

SUBJECT: Forwards corrected response to 800312 ltr, Item 4, re address info available to operator following various NNI/ICS power events.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: General Distribution for after Issuance of Operating Lic

NOTES: ~~M. CUNNINGHAM - ALL AMENDMENTS TO~~
~~CHANGES TO TECH SPEC. R. CAPRA - 1C7~~

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR ENCL	LTR ENCL	ID CODE/NAME		LTR ENCL	
05 BC	ORB#4	7	7				
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1	
	12 I&E	2	2	15 CORE PERF BR	1	1	
	17 ENGR BR	1	1	18 REAC SFTY BR	1	1	
	19 PLANT SYS BR	1	1	20 EEB	1	1	
	21 EFLT TRT SYS	1	1	EPB-DOR	1	1	
	DELD	1	0	STS GROUP LEADR	1	1	
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1	
	23 ACRS	16	16				

Ltr + Encl

Ltr + Encl

O. GISENHUT
 R. TERPESCO
 J. OLSHINSKI
 G. LAINAS
 J. BEARD
 J. T TELFORD
 S. DIAB
 T. NOVAK
 R. SCATTERFIELD
 D. THATCHER
 V PANCIERA
 D TONI

R. CAPRA
 B. SHERON
 V PANCIERA
 D QUICK(IE)
 E. BLACKWOOD
 J. MURPHY
 V. MOORE
 B. SNYDER
 H. ORNSTEIN

MAR 24 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR

60 59
 28 ENCL 37

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 17, 1980

TELEPHONE: AREA 704
373-4083

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555


Attention: Mr. R. W. Reid, Chief
Operating Reactors Branch No. 4

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

Dear Sir:

My letter of March 12, 1980 concerning the recent event at Crystal River and the response by Duke Power to the event contained an incorrect response. The correct response to Item 4, "Address information available to the operator following various NNI/ICS power upset events . . ." is provided in the attached.

Very truly yours,



William O. Parker, Jr.

RLG:scs

Attachment

8003200449

A001
S
1/1
ADD
LIST

4. Address information available to the operator following various NNI/ICS power upset events, including:

- how the operator determines which information is reliable
- what information is needed for cold shutdown.

Following the November event at Unit 3, a procedure was developed to address loss of ICS power. This procedure provides specific information as to what indications are reliable.

This list of information needed for cold shutdown is contained in our response to IE Bulletin 79-27 which was submitted by W. O. Parker's letter dated March 7, 1980 to J. P. O'Reilly, Director, Region II.