

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912060502 DOC. DATE: 79/12/03 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.

DOCKET #
 05000269
 05000270
 05000287

AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: DENTON, H.R. RECIPIENT AFFILIATION: Office of Nuclear Reactor Regulation

SUBJECT: Requests addl time to respond to NRC 791121 ltr re small break LOCA. Info re mechanical effects of induced slug flow on steam generator tubes will be provided by 800215. Pump seal cooling info will be submitted by 791231.

DISTRIBUTION CODE: A041S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Resp to Lesson Learn Task Force - B&W and 50-409

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	8 BC ORB #4	7		
INTERNAL:	REG FILE	1	15 I & E	2
	17 TA/EDU	1	18 CORE PERF BR	1
	19 ENG BR	1	2 NRC PDR	1
	20 REAC SFTY BR	1	21 PLANT SYS BR	1
	22 EEB	1	23 EFLT TRT SYS	1
	3 LPDR	1	4 NSIC	1
	5 C LONG	1	6 G LANIK	1
	7 J DONOHEW	1	0 CHOPRA	1
	OELD	1		
EXTERNAL:	24 ACRS	16		16

JAN 14 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 41 ENCL 0

Mac

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 3, 1979

TELEPHONE: AREA 704
373-4083

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Mr. R. W. Reid, Chief
Operating Reactors Branch No. 4

Re: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

Dear Sir:

With regard to your letter dated November 21, 1979 which requests additional information concerning small break loss of coolant accident, additional time is required to provide a complete response to the letter. A response to Item 1 addressing the mechanical effects of induced slug flow on steam generator tubes will be provided by February 15, 1980; a response to Item 3 addressing RC pump seal cooling will be provided by December 31, 1979.

Very truly yours,


William O. Parker, Jr.

RLG:scs

7912060502

A041
S
1/0