

Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 8/31/2015)

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
ME9020	RIS 'Embedded Digital Devices in Safety Systems'	38.0	07/09/2012	NRO
MF0581	GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools'	32.0	01/29/2013	DSS
MF3182	RIS 'Seismic Analysis Methods for Spent Fuel Dry Cask Loading Stack-up Configuration'	21.0	12/05/2013	NMSS
MF3949	RIS 'RIS 2005-29 Rev 1 Anticipated Transients That Could Develop into More Serious Events'	17.0	04/17/2014	DSS
MF4346	RIS 'Pressure Boundary Leakage'	15.0	07/02/2014	NRO
MF5565	RIS 'PCT Reporting Required by 50.46'	8.0	01/13/2015	DSS
MF5620	RIS 'PAR for Members of Public on Bodies of Water'	7.0	01/28/2015	DPR
MF5661	RIS 'Safety-Related SSCs in Service Beyond Service Life'	7.0	02/03/2015	PGCB
MF5782	RIS 'Accreditation Procurement of Laboratory Calibration and Test Services'	6.0	02/25/2015	PGCB
MF5828	RIS 'UFSAR Submittals'	6.0	03/10/2015	PGCB
MF5865	IN 'Snubber Lubricant Degradation Issues'	5.0	03/19/2015	PGCB
MF6041	RIS 'Crediting Mitigating Strategies in the SDP'	5.0	03/31/2015	PGCB
MF6131	RIS 'Clarification of the Requirements of 10 CFR 37.11b Specific Exemptions'	4.0	04/23/2015	PGCB

**Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 8/31/2015)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF6150	IN '10 CFR 50.59 Finding Regarding Circuit Board with Complex Programmable Logic Device'	4.0	04/28/2015	PGCB
MF6195	RIS 'ASME Code Relief Request'	4.0	05/06/2015	PGCB
MF6204	IN 'Design Basis Issues Relating to Tube to Tube Sheet Joints in PWR Steam Generators'	4.0	05/08/2015	PGCB
MF6331	RIS 'Highlights of Aspects in 10 CFR 50.59 Related to Issues Identified in SONGS Paper'	3.0	06/09/2015	PGCB
MF6357	RIS 'Compensatory Measures for Protective Strategy Deficiencies'	3.0	06/16/2015	PGCB
MF6471	IN 'Unaccounted for Error Terms w/ Irradiation Testing'	1.5	07/14/2015	PGCB
MF6487	IN 'Main Steam Isolation Valve Failures'	1.5	07/20/2015	PGCB
MF6496	RIS 'Containment Liner Moisture Barrier Inspection'	1.5	07/21/2015	PGCB
MF6625	RIS 'Design Basis Issues Related to Tube-to-Tubesheet Joints in PWR Steam Generators'	.5	08/20/2015	PGCB
MF6626	RIS 'Notice of Issuance of EGM – EP and EPIP Updates'	.5	08/20/2015	PGCB