

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 436

FILE: INCIDENT FILE

FROM: Duke Power Co. Charlotte, N.C. W.O. Parker, Jr.			DATE OF DOC 1-13-76	DATE REC'D 1-20-76	LTR XXX	TWX	RPT	OTHER
TO: N.C. Moseley			ORIG 1 Signed	CC 0	OTHER	SENT MRC PDR XXX		SENT LOCAL PDR XXX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-270		

## DESCRIPTION:

Supplement Unusual Event Report # 75-17,  
Concerning the inadvertent isolation of letdown  
flow....

(1 Cy. Received)

PLANT NAME: Oconee # 2

## ENCLOSURES:

**DO NOT REMOVE  
ACKNOWLEDGED**

FOR ACTION/INFORMATION

SAB 1-23-76

BRANCH CHIEF Purple

LIC. ASST. Sheppard W/16 cys ACRS

## INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I&E (2)

MLPC (3)

SCHRODER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/SCHWENCER

CASE

F. WILLIAMS

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH  
KREGER/J. COLLINS

NOTE: IF PERSONEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

## EXTERNAL DISTRIBUTION

LOCAL PDR Walhalla, S.C.

TIC

NSIC

DISTRIBUTION REVISED 1-19-76 by D. CRUTCHFIELD, TECH REVIEW COORDINATOR

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

January 13, 1976

Mr. Norman C. Moseley, Director  
U. S. Nuclear Regulatory Commission  
Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303


Re: Oconee Unit 2  
Docket No. 50-270

Dear Mr. Moseley:

The following information is submitted to supplement Unusual Event Report UE-270/75-17 concerning an incident involving the inadvertent isolation of letdown flow:


Originally, this incident was reported to have resulted from a misunderstanding between personnel involved. A contributing cause, however, was the lack of adequate procedural control to prevent unauthorized personnel from performing functions which may affect unit or station operation. To prevent future incidents of this type, Oconee Administrative Procedure Number 5 has been revised to assure more accurate communication between operating and maintenance personnel and in particular to delineate responsibilities for the operation of station valves. The procedure requires that the Control Operator be notified prior to the performance of any function affecting operation or Control Room indications, and that the Shift Supervisor be notified prior to removing an instrument or component from service or returning it to service. Also, with certain exceptions as listed in the procedure, no personnel other than operators shall be allowed to operate station valves without permission from the Shift Supervisor.

Very truly yours,

  
William O. Parker, Jr.

EDB:mmb

CC Mr. Benard C. Rusche



436