



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION I
2100 RENAISSANCE BOULEVARD, SUITE 100
KING OF PRUSSIA, PA 19406-2713

January 22, 2016

Docket No. 03020243

License No. 47-23076-01

Donald Atkins
Corporate Radiation Safety Officer
Huntington Testing & Technology
1200 Airport Road
Huntington, WV 25704

SUBJECT: NRC INSPECTION REPORT NO. 03020243/2015002, HUNTINGTON TESTING & TECHNOLOGY, HUNTINGTON, WEST VIRGINIA SITE, HOBART, INDIANA SITE, AND THE MOUNTAINEER FABRICATORS, NITRO, WEST VIRGINIA, AND NOTICE OF VIOLATION

Dear Mr. Atkins:

On September 15, 2015, John Miller of this office commenced a safety and security inspection at the above address and at a temporary jobsite at Mountaineer Fabricators located in Nitro, West Virginia. Ryan Craffey from NRC Region 3 conducted a safety and security inspection at your facility located at 1931 Northwind Parkway, Hobart, Indiana. The inspection continued in-office through January 12, 2016. The inspection was an examination of your licensed activities as they relate to the safety and security of radioactive material and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with you at the conclusion of the inspection on a teleconference on January 12, 2016.

Based on the results of this inspection, the NRC has determined that five Severity Level IV violations of NRC requirements occurred. The violations were evaluated in accordance with the NRC Enforcement Policy which can be found at the NRC's Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/enforce-pol.html>. The violations involved security requirements found in Title 10 of the *Code of Federal Regulations* (10 CFR) Part 37. The violations are cited in the enclosed non-public Notice of Violation (Notice) because they were identified by the NRC during the inspection.

You are required to respond to this letter and must follow the instructions specified in the enclosed Notice when preparing your response. The guidance in NRC Information Notice 96-28, "Suggested Guidance Relating to Development and Implementation of Corrective Action," may be helpful. You can find the Information Notice on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/info-notices/1996/in96028.html>.

Information regarding the reason for the violations, the corrective actions taken and planned to correct the violations and prevent recurrence, and the date when full compliance will be (was)

Enclosure contains Sensitive Unclassified Non-Safeguards Information. Upon separation, this cover letter is decontrolled.
--

D. Atkins

2

achieved should be addressed. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

The Enclosed Notice contains Security-Related Information under 10 CFR 2.390(d)(1), and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the material in the enclosure will not be made available electronically for public inspection in the NRC Public Document Room or in the NRC's Agencywide Document Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If Security-Related Information is necessary to provide an acceptable response, please mark your entire response Security-Related Information in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Please contact John Miller at 610-337-5089 if you have any questions regarding this matter.

Sincerely,

/RA/

Blake D. Welling, Chief
Commercial, Industrial, R&D
and Academic Branch
Division of Nuclear Materials Safety

Enclosure:
Notice of Violation

cc w/o Enclosure: Jay Goodyear
State of West Virginia

D. Atkins

2

achieved should be addressed. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

The Enclosed Notice contains Security-Related Information under 10 CFR 2.390(d)(1), and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the material in the enclosure will not be made available electronically for public inspection in the NRC Public Document Room or in the NRC's Agencywide Document Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If Security-Related Information is necessary to provide an acceptable response, please mark your entire response Security-Related Information in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Please contact John Miller at 610-337-5089 if you have any questions regarding this matter.

Sincerely,

/RA/

Blake D. Welling, Chief
Commercial, Industrial, R&D
and Academic Branch
Division of Nuclear Materials Safety

Enclosure:
Notice of Violation

cc w/o Enclosure: Jay Goodyear
State of West Virginia

Distribution:
B. Bickett, RI

DOCUMENT NAME: G:\WordDocs\Mailed\Insp Letter\Huntington Public Ltr.docx

ML16025A122

After declaring this document "An Official Agency Record" it **will** be released to the Public.

To receive a copy of this document, indicate in the box: C = Copy w/o attach/encl E = Copy w/ attach/encl N = No copy

OFFICE	DNMS/RIII	N	DNMS/RI	DNMS/RI		
NAME	RCraffey/JJM f/		JMiller/JJM	BWelling/bdw		
DATE	01/20/16		01/20/16	01/22/16		

OFFICIAL RECORD COPY