



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION IV
1600 E. LAMAR BLVD.
ARLINGTON, TX 76011-4511

April 6, 2016

Mr. Mark E. Reddemann
Chief Executive Officer
Energy Northwest
P.O. Box 968 (Mail Drop 1023)
Richland, WA 99352-0968

SUBJECT: COLUMBIA GENERATING STATION – NRC MATERIAL CONTROL AND
ACCOUNTING PROGRAM INSPECTION REPORT 05000397/2016405

Dear Mr. Reddemann:

On March 3, 2016, the U.S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at the Columbia Generating Station. The inspection covered a key attribute of the Security Cornerstone of the NRC's Reactor Oversight Process, Material Control and Accounting of Special Nuclear Material. The enclosed inspection report documents the inspection results, which were discussed on March 3, 2016, with Mr. A. L. Javorik, Vice President, Engineering, and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

The NRC inspectors documented one finding of very low security significance (i.e., Green as determined by the Baseline Security Significance Determination Process for Power Reactors) in this report. This finding involved a violation of NRC requirements. Further, inspectors documented a licensee-identified violation which was determined to be of very low security significance (i.e., Green as determined by the Baseline Security Significance Determination Process for Power Reactors) in this report. The NRC is treating these violations as non-cited violations (NCVs) consistent with Section 2.3.2.a of the NRC Enforcement Policy.

If you contest the violations or significance of these NCVs, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001; with copies to the Regional Administrator, Region IV; the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the Columbia Generating Station.

"Enclosure transmitted herewith contains SUNSI. When separated from enclosure, this transmittal document is decontrolled."

~~OFFICIAL USE ONLY - SECURITY-RELATED INFORMATION~~

M. Reddemann

- 2 -

If you disagree with the cross-cutting aspect assignment in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the Regional Administrator, Region IV; and the NRC Resident Inspector at the Columbia Generating Station.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice and Procedure," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's document system, (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Heather J. Gepford, Ph.D., CHP, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket No. 50-397
License No. NPF-21

Nonpublic Enclosure:
Inspection Report 05000397/2016405
w/Attachment: Supplemental Information

cc w/enclosure:
Kurt Gosney, Manager, Security
Columbia Generating Station
MD988C, WNP2 plant Warehouse
76N. Power Plant Loop
Richland, WA 99354

cc w/o enclosure: Electronic Distribution

~~OFFICIAL USE ONLY - SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

M. Reddemann

- 2 -

If you disagree with the cross-cutting aspect assignment in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the Regional Administrator, Region IV; and the NRC Resident Inspector at the Columbia Generating Station.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice and Procedure," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's document system, (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Heather J. Gepford, Ph.D., CHP, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket No. 50-397
License No. NPF-21

Nonpublic Enclosure:
Inspection Report 05000397/2016405
w/Attachment: Supplemental Information

cc w/enclosure:
Kurt Gosney, Manager, Security
Columbia Generating Station
MD988C, WNP2 plant Warehouse
76N. Power Plant Loop
Richland, WA 99354

cc w/o enclosure: Electronic Distribution

Distribution: See next page

ADAMS ACCESSION NUMBER: ML16098A475

Entire Report: <input checked="" type="checkbox"/> SUNSI Review: HGepford		<input type="checkbox"/> Non-Sensitive <input checked="" type="checkbox"/> Sensitive		<input type="checkbox"/> Publicly Available <input checked="" type="checkbox"/> Non-Publicly Available		Keyword: MD 3.4 Non-Public A.3	
Cover Letter Only: <input checked="" type="checkbox"/> SUNSI Review: HGepford		<input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Sensitive		<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available		Keyword: SUNSI Review Complete	
OFFICE	PSB2	C:DRP/A	C:PSB2				
NAME	JO'Donnell	JGroom	HGepford				
SIGNATURE	/RA/	/RA/ REL for	/RA/				
DATE	4/4/16	4/6/16	4/6/16				

OFFICIAL RECORD COPY

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

Letter to Mark E. Reddemann from Heather J. Gepford, dated April 6, 2016

SUBJECT: COLUMBIA GENERATING STATION – NRC MATERIAL CONTROL AND
ACCOUNTING PROGRAM INSPECTION REPORT 05000397/2016405

Distribution w/enclosure:

Security Specialist/NSIR (Eric.Wharton@nrc.gov)
Security Specialist/NSIR (Niry.Simonian@nrc.gov)
Chief, Security Performance Evaluation Branch/NSIR (Clay.Johnson@nrc.gov)
Security Specialist/NSIR (Douglas.Garner@nrc.gov)
Branch Chief, RI DRS/PSB1 (Raymond.McKinley@nrc.gov)
Branch Chief, RII DRS/PSB2 (Binoy.Desai@nrc.gov)
Branch Chief, RIII DRS/PSB (Steven.Orth@nrc.gov)
Senior Resident Inspector (Gregory.Kolcum@nrc.gov)

Distribution w/o enclosure:

Regional Administrator (Marc.Dapas@nrc.gov)
Deputy Regional Administrator (Kriss.Kennedy@nrc.gov)
DRP Director (Troy.Pruett@nrc.gov)
DRP Deputy Director (Ryan.Lantz@nrc.gov)
DRS Director (Anton.Vegel@nrc.gov)
DRS Deputy Director (Jeff.Clark@nrc.gov)
Senior Resident Inspector (Gregory.Kolcum@nrc.gov)
Senior Resident Inspector (Dan.Bradley@nrc.gov)
Branch Chief, DRP/A (Jeremy.Groom@nrc.gov)
Senior Project Engineer, DRP/A (Ryan.Alexander@nrc.gov)
Project Engineer (Thomas.Sullivan@nrc.gov)
Project Engineer (Matthew.Kirk@nrc.gov)
Site Administrative Assistant (Vacant)
Public Affairs Officer (Victor.Dricks@nrc.gov)
Project Manager (John.Klos@nrc.gov)
Team Leader, DRS/IPAT (Thomas.Hipschman@nrc.gov)
RITS Coordinator (Marisa.Herrera@nrc.gov)
ACES (R4Enforcement.Resource@nrc.gov)
Acting Regional Counsel (Emily.Monteith@nrc.gov)
Technical Support Assistant (Loretta.Williams@nrc.gov)
Senior Congressional Affairs Officer (Jenny.Weil@nrc.gov)
RIV Congressional Affairs Officer (Angel.Moreno@nrc.gov)
RIV/ETA: OEDO (Jeremy.Bowen@nrc.gov)
ROPreports.Resource@nrc.gov
ROPassessment.Resource@nrc.gov

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~