



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION III  
2443 WARRENVILLE RD. SUITE 210  
LISLE, IL 60532-4352

APR 15 2016

Michael F. Busch, M.D.  
Radiation Safety Officer  
Franciscan St. Elizabeth Health Lafayette  
Nuclear Medicine Department  
1701 S. Creasy Lane  
Lafayette, IN 47905

Dear Dr. Busch:

Enclosed is Amendment No. 67 to your NRC Material License No. 13-09788-01 in accordance with your request. Please note that the changes made to your license are printed in **bold** font.

In addition, the NRC staff has reviewed your final status surveys provided in NRC Form 314 'Certificate of Disposition' dated January 11, 2016, request to terminate NRC License Number 13-26527-01. Based on its review, the staff has concluded that residual radioactive material attributable to licensed activities does not exceed current NRC criteria. Based on these conclusions no further remediation or actions with respect to NRC regulated material is required. This facility has been added to NRC license number 13-09788-01 and NRC license number 13-26527-01 is hereby terminated.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.


The NRC's Safety Culture Policy Statement became effective in June 2011. While a policy statement and not a regulation, it sets forth the agency's *expectations* for individuals and organizations to establish and maintain a positive safety culture. You can access the policy statement and supporting material that may benefit your organization on NRC's safety culture Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/safety-culture.html>. We strongly encourage you to review this material and adapt it to your particular needs in order to develop and maintain a positive safety culture as you engage in NRC-regulated activities.

M. F. Busch, M.D.

-2-

In accordance with 10 Code of Federal Regulations 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer L. Bishop". The signature is fluid and cursive, with the first name "Jennifer" being more prominent than the last name "Bishop".

Jennifer L. Bishop  
Health Physicist  
Materials Licensing Branch

License No. 13-09788-01 and 13-26527-01  
Docket No. 030-01642 and 030-33299

Enclosure: 1. Amendment No. 67 for License No. 13-09788-01  
2. Amendment No. 09 for License No. 13-26527-01