



ND-2016-0003  
May 4, 2016

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Subject: **PSEG Early Site Permit Application**  
**Docket No. 52-043**  
**Submittal of Errata Page to Revision 4 of the Early Site Permit**  
**Application for the PSEG Site**

- References:
- 1) PSEG Power, LLC Letter No, ND-2015-0009 to USNRC, Submittal of Revision 4 of the Early Site Permit Application for the PSEG Site, dated June 5, 2015
  - 2) RAI No. 61, SRP Section: 02.05.02 – Vibratory Ground Motion, dated June 7, 2012 (eRAI 6488)
  - 3) PSEG Power, LLC Letter No, ND-2012-0057 to USNRC, Response to Request for Additional Information, RAI No. 61, Vibratory Ground Motion, dated October 2, 2012
  - 4) PSEG Power, LLC Letter No, ND-2012-0073 to USNRC, Response to Request for Additional Information, RAI No. 61, Vibratory Ground Motion, dated October 26, 2012
  - 5) PSEG Power, LLC Letter No, ND-2012-0079 to USNRC, Response to Request for Additional Information, RAI No. 61, Vibratory Ground Motion, dated December 20, 2012
  - 6) PSEG Power, LLC Letter No, ND-2013-0002 to USNRC, Response to Request for Additional Information, RAI No. 61, Vibratory Ground Motion, dated January 11, 2013

DO79  
NRD

The purpose of this letter is to provide an errata page to Revision 4 of the Early Site Permit Application (ESPA) for the PSEG Site provided in Reference 1 above. This errata page updates the list of figures provided in Chapter 2, Site Characteristics and Site Parameters, of the Site Safety Analysis Report (SSAR), as submitted in Part 2 of the PSEG Site Early Site Permit Application, Revision 4.

PSEG identified an oversight in the submittal of responses (References 3, 4, 5 and 6) to the request for additional information (RAI) provided in Reference 2 above. The responses to RAI No. 61 deleted SSAR Figures 2.5.2-1 through 2.5.2-17 from the ESPA. The SSAR Chapter 2 list of figures was not updated to reflect the deletion of these figures from the ESPA in subsequent ESPA revision submittals.

Enclosure 1 provides the errata page to Revision 4 of the Early Site Permit Application.

If any additional information is needed, please contact David Robillard, PSEG Nuclear Development Licensing Engineer, at (856) 339-7914.

I declare under penalty of perjury that the foregoing is true and correct. Executed on the 4<sup>th</sup> day of May, 2016.

Sincerely,



James Mallon  
Early Site Permit Manager  
Nuclear Development  
PSEG Power, LLC

Enclosure 1: Errata Page for SSAR Chapter 2, Site Characteristics and Site Parameters

cc: USNRC Project Manager, Division of New Reactor Licensing, PSEG Site  
(w/enclosures)  
USNRC Environmental Project Manager, Division of New Reactor Licensing  
(w/enclosures)  
USNRC Region I, Regional Administrator (w/enclosures)

**PSEG Letter ND-2016-0003, dated May 4, 2016**

**ENCLOSURE 1**

**Errata Page for SSAR Chapter 2, Site Characteristics and Site Parameters**

**PSEG Site  
ESP Application  
Part 2, Site Safety Analysis Report**

LIST OF FIGURES (CONTINUED)

<u>Number</u>	<u>Title</u>
2.5.1-37	Geotechnical Boring Location
2.5.1-38	Cross-Section A-A'
2.5.1-39	Cross-Section B-B'
2.5.1-40	Structure Contour Map – Top of Vincentown Formation
2.5.2-1	Not Used
2.5.2-2	Not Used
2.5.2-3	Not Used
2.5.2-4	Not Used
2.5.2-5	Not Used
2.5.2-6	Not Used
2.5.2-7	Not Used
2.5.2-8	Not Used
2.5.2-9	Not Used
2.5.2-10	Not Used
2.5.2-11	Not Used
2.5.2-12	Not Used
2.5.2-13	Not Used
2.5.2-14	Not Used
2.5.2-15	Not Used
2.5.2-16	Not Used
2.5.2-17	Not Used
2.5.2-18	Mean and Fractile Rock Seismic Hazard Curves for PGA

Rev. 4