

**KHNP****KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

May 9, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-0468L

Subject: Revised Response to RAI 199-8223 for the Question 03.08.01-11

References: 1) NRC Request for Additional Information 199-8223, dated September 8, 2015
2) KHNP Letter MKD/NW-16-0019L, Response to RAI 199-8223, dated January 8, 2016

KHNP is hereby submitting the revised response to RAI 199-8223, dated September 8, 2015. The RAI revised response addresses Question 03.08.01-11 in response to the bi-weekly seismic call with NRC, dated March 23, 2016. It addresses the four loads that exist in the ACI load combination, but do not exist in the ASME load combination and clarifies the effect of the soil pressure on the RCB foundation.

The enclosure provides the revised response to RAI 199-8223 for the Question 03.08.01-11 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 199-8223 for the Question 03.08.01-11 (Non-Proprietary)

Enclosure

Revised Response to RAI 199-8223 for the Question 03.08.01-11

(Non-Proprietary)

May 9, 2016