

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 30, 1979

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303


Re: Oconee Unit 3
Docket No. 50-287

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-287/79-13. This report is submitted pursuant to Oconee Nuclear Station Technical Specifications 6.2 and 6.6.2.1.a(2), which concerns operation when a parameter subject to a limiting condition for operation is less conservative than the least conservative aspect of the limiting condition for operation, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

My letter of November 23, 1979 addressed the delays in the preparation of this report.

Very truly yours,



William O. Parker, Jr.

SRL/sch
Attachment

cc: Director, Office of Management Information
and Program Control



7912070 439

A002
S
1/1