

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

February 5, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287

Dear Sir:

My letter of January 22, 1980 informed you of delays involved in the preparation of Reportable Occurrence Report RO-269/80-1. That report, which deals with effects of airborne activity on Control Room habitability analyses, is attached. This report is submitted pursuant to Section 6.6.2.1.a (8) of the Oconee Nuclear Station Technical Specifications and describes an analysis omission when the original analyses of Control Room habitability were performed. This omission is not considered to have had an adverse impact on public health and safety.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

KRW:scs

Attachment

*1002  
5/1*

80-021 20749