

Wanda

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

July 16, 1980

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Unit 3
50-287

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report R0-287/80-11 which addresses an item which is considered to be a potential degradation of the reactor coolant pressure boundary and is thus reportable under Technical Specification 6.6.2.1.a(3). Based on the review of this occurrence, Duke Power Company considers that continued operation of the plant will present no hazard to the health and safety of the public.

My letter of July 8, 1980 addressed the delay in the preparation of this report.

Very truly yours,


William O. Parker, Jr.

FTP:vr
Attachment

cc: Director
Office of Management & Program Analysis
USNRC
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

8008210394

5

A002
S
1/1

OFFICIAL COPY.