



Cynthia R. Hafenstine  
Manager Regulatory Affairs

May 5, 2016

RA 16-0042

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Subject: Docket No. 50-482: Revision of Four Forms that Implement the Radiological Emergency Response Plan (RERP) for Wolf Creek Generating Station (WCGS)

Gentlemen:

Four forms that implement the WCGS RERP have been revised. The revised forms are identified below:

<u>Forms</u>	<u>Effective Dates</u>	<u>Forms</u>	<u>Effective Dates</u>
EPF 06-018-10, rev. 10A	April 11, 2016	EPF 06-018-17, rev. 4A	April 11, 2016
EPF 06-018-15, rev. 13A	April 11, 2016	EPF 06-001-08, rev. 1	April 19, 2016

The attached summary of the changes to the implementing forms explains that these changes do not reduce the effectiveness of the WCGS RERP. This letter contains no commitments. If you have any questions concerning this matter, please contact me at (620) 364-4204.

Sincerely,

*Cynthia R. Hafenstine*  
Cynthia R. Hafenstine

CRH/rlt

Attachment: Summary of Changes to Four Forms That Implement the Wolf Creek Generating Station (WCGS) Radiological Emergency Response Plan (RERP)

cc: M. L. Dapas (NRC), w/a  
C. F. Lyon (NRC), w/a  
N. H. Taylor (NRC), w/a  
Senior Emergency Preparedness Inspector (NRC), w/a  
Senior Resident Inspector (NRC), w/a

AX45  
NRR

**Summary of Changes to Four Forms That Implement the Wolf Creek Generating Station (WCGS) Radiological Emergency Response Plan (RERP)**

**1. Form EPF 06-018-10, "Wolf Creek Phone Team Room Inventory Checklist," Rev. 10A.**

The number of media monitoring team compact discs (CDs) has been changed from five to four. This change is administrative in nature and, therefore, does not decrease the effectiveness of the WCGS RERP.

**2. Form EPF 06-018-15, "Emergency Planning Quarterly Communications Checklist," Rev. 13A.**

Telephone numbers have been changed for locations listed in this form. This change is administrative in nature and, therefore, does not decrease the effectiveness of the WCGS RERP.

**3. Form EPF 06-018-17, "Topeka Phone Team Room Inventory Checklist," Rev. 4A.**

The number of media monitoring team CDs has been changed from five to four. This change is administrative in nature and, therefore, does not decrease the effectiveness of the WCGS RERP.

**4. Form EPF 06-001-08, "Off-Site Communicator Checklist," Rev. 1.**

A telephone number for the facsimile machine at the Alternate Technical Support Center (TSC) has been added in support of the emergency notification process in the event the Alternate TSC is activated. The name of the contact for one of the owners of WCGS has been changed to Westar Generation Operations. These changes provide additional guidance for on-shift personnel who perform the Notification/Communication function and, therefore, do not reduce the effectiveness of the WCGS RERP.