

Director of FSMA
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Notification of Proper Disposal of Tritium Exit Signs

This letter is to provide notification that the signs listed on the attached documents have been shipped to SRB Technologies, Inc. (NC Radioactive Materials License # 034-0534-2) for proper disposal.

These signs were originally installed at:

Susitna Elementary School
7500 Tyone Ct
Anchorage, AK 99504

Sincerely,

Alan Caldwell



Signature - Installation facility

October 7, 2016
Date

Operations Manager
Title

TRITIUM EXIT SIGNS INVENTORY SHEET 1/5

| | MFG | MODEL | SERIAL NUMBER | MFG DATE | LIFE |
|----|--------------|--------|---------------|----------|------|
| 1 | Saftey Signs | B100 | 632470 | 8/1/98 | 20 |
| 2 | Saftey Signs | B100 | 632466 | 8/1/98 | 20 |
| 3 | Saftey Signs | B100 | 632478 | 8/1/98 | 20 |
| 4 | Saftey Signs | b100 | 632467 | 8/1/98 | 20 |
| 5 | Perm-Ex | T-4001 | A2AQ169 ✓ | 12/1/00 | 25 |
| 6 | Perm-Ex | T-4001 | A2AQ170 ✓ | 12/1/00 | 25 |
| 7 | ISOLITE | 2040 | A851532 ✓ | 5/1/98 | 11.5 |
| 8 | ISOLITE | 2040 | A85801 ✓ | 5/1/98 | 11.5 |
| 9 | ISOLITE | 2040 | A851527 ✓ | 5/1/98 | 11.5 |
| 10 | ISOLITE | 2040 | A851530 ✓ | 5/1/98 | 11.5 |

TRITIUM EXIT SIGNS INVENTORY SHEET 2/5

| | MFG | MODEL | SERIAL NUMBER | MFG DATE | LIFE |
|----|---------|----------|---------------|----------|------|
| 1 | ISOLITE | 2000 | A961186 ✓ | 6/1/99 | 11.5 |
| 2 | ISOLITE | 880-12-6 | 11-5429 ✓ | 3/1/11 | 20 |
| 3 | ISOLITE | 880-12-6 | 11-5428 ✓ | 3/1/11 | 20 |
| 4 | ISOLITE | 880-12-6 | 11-5438 ✓ | 3/1/11 | 20 |
| 5 | ISOLITE | 880-12-6 | 11-5439 ✓ | 3/1/11 | 20 |
| 6 | ISOLITE | 880-12-6 | 11-5436 ✓ | 3/1/11 | 20 |
| 7 | ISOLITE | 880-12-6 | 11-5441 ✓ | 3/1/11 | 20 |
| 8 | ISOLITE | 880-12-6 | 11-5435 ✓ | 3/1/11 | 20 |
| 9 | ISOLITE | 880-12-6 | 11-5437 ✓ | 3/1/11 | 20 |
| 10 | ISOLITE | 2040 | A22012 ✓ | 2/1/02 | 11.5 |

TRITIUM EXIT SIGNS INVENTORY SHEET 3/5

| | MFG | MODEL | SERIAL NUMBER | MFG DATE | LIFE |
|----|---------|----------|---------------|----------|--------|
| 1 | ISOLITE | 2000 | A22011 ✓ | 2/1/02 | 2/1/02 |
| 2 | ISOLITE | 880-12-6 | 11-2479 ✓ | 3/1/11 | 3/1/11 |
| 3 | ISOLITE | 880-12-6 | 11-2480 ✓ | 3/1/11 | 3/1/11 |
| 4 | ISOLITE | 880-12-6 | 11-2473 ✓ | 3/1/11 | 3/1/11 |
| 5 | ISOLITE | 2040 | A961175 ✓ | 6/1/99 | 6/1/99 |
| 6 | ISOLITE | 2040 | A961176 ✓ | 6/1/99 | 6/1/99 |
| 7 | ISOLITE | 2040 | A961189 ✓ | 6/1/99 | 6/1/99 |
| 8 | ISOLITE | 2040 | A961188 ✓ | 6/1/99 | 6/1/99 |
| 9 | ISOLITE | 2040 | A961174 ✓ | 6/1/99 | 6/1/99 |
| 10 | ISOLITE | 880-12-6 | 11-2476 ✓ | 2/1/11 | 2/1/11 |

TRITIUM EXIT SIGNS INVENTORY SHEET 4/5

| | MFG | MODEL | SERIAL NUMBER | MFG DATE | LIFE |
|----|---------|----------|---------------|----------|------|
| 1 | ISOLITE | 880-12-6 | 11-5427 ✓ | 3/1/11 | 20 |
| 2 | ISOLITE | 880-12-6 | 11-2475 ✓ | 2/1/11 | 20 |
| 3 | ISOLITE | 880-12-6 | H39087 ✓ | 3/1/15 | 20 |
| 4 | ISOLITE | 2040 | A961173 ✓ | 6/1/99 | 11.5 |
| 5 | ISOLITE | 2040 | A961170 ✓ | 6/1/99 | 11.5 |
| 6 | ISOLITE | 2040 | A961190 ✓ | 6/1/99 | 11.5 |
| 7 | ISOLITE | 2040 | A961187 ✓ | 6/1/99 | 11.5 |
| 8 | ISOLITE | 2000 | A961182 ✓ | 6/1/99 | 11.5 |
| 9 | ISOLITE | 880-12-6 | 11-5440 ✓ | 3/1/11 | 20 |
| 10 | ISOLITE | 880-12-6 | 11-5430 ✓ | 3/1/11 | 20 |

TRITIUM EXIT SIGNS INVENTORY SHEET 5/5

| | MFG | MODEL | SERIAL NUMBER | MFG DATE | LIFE |
|----|---------|----------|---------------|----------|------|
| 1 | ISOLITE | 880-12-6 | 11-5432 ✓ | 3/1/11 | 20 |
| 2 | ISOLITE | 880-12-6 | 11-5426 ✓ | 3/1/11 | 20 |
| 3 | ISOLITE | 880-12-6 | 11-5431 ✓ | 3/1/11 | 20 |
| 4 | ISOLITE | 2000 | A961177 ✓ | 6/1/99 | 11.5 |
| 5 | ISOLITE | 880-12-6 | 11-5434 ✓ | 3/1/11 | 20 |
| 6 | ISOLITE | 2000 | A961172 ✓ | 6/1/99 | 11.5 |
| 7 | | | | | |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |