

**KHNP****KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

November 1, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-1072L

Subject: Second Supplemental Response to RAI 92-8068 for Question 03.09.05-16

References: 1) NRC Request for Additional Information 92-8068, dated July 21, 2015
2) KHNP Letter MKD/NW-15-0195L, Response to RAI 92-8068, dated October 16, 2015
3) KHNP Letter MKD/NW-16-0022L, Supplemental Response to RAI 92-8068, dated February 19, 2016

KHNP is hereby submitting a second supplemental response to RAI 92-8068, dated July 21, 2015. The supplemental RAI response addresses Question 03.09.05-16 to provide the upset events that result in a discharge of the in-containment refueling water storage tank (IRWST). The enclosure provides the second supplemental response to RAI 92-8068 for Question 03.09.05-16 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Second Supplemental Response to RAI 92-8068 for Question 03.09.05-16 (Non-Proprietary)

Enclosure

Second Supplemental Response to RAI 92-8068 for
Question 03.09.05-16

(Non-Proprietary)

November 1, 2016