

Receptor: Man camp
ECL ratios are unitless

Receptor: CBM Worker
ECL ratios are unitless

Receptor: T-Chair
ECL ratios are unitless

[illegible]

Receptor: CBM Worker
ECL ratios are unitless

ECL Ratios: Time Step 5

Receptor: T-Chair
ECL ratios are unitless

08/23/2016

08/23/2016

08/23/2016

08/23/2016

[illegible]

08/23/2016

08/23/2016

Receptor: T-Chair
ECL ratios are unitless

Receptor: Dry Fork
ECL ratios are unitless

Receptor: Pumpkin Butte
ECL ratios are unitless

08/23/2016

Receptor: Pumpkin Butte
ECL ratios are unitless

Receptor: Man camp
ECL ratios are unitless

Receptor: CBM Worker
ECL ratios are unitless

08/23/2016

Jane Dough PA2 wellfield leak	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00
Total	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	0.00E+00	9.31E-05	0.00E+00	0.00E+00	0.00E+00	0.00E+00

Receptor: Man camp
ECL ratios are unitless

Receptor: CBM Worker
ECL ratios are unitless

08/23/2016