



Axiall Corporation
P.O. Box 191
New Martinsville, WV 26155

Jerry Mullens
Works Manager
Telephone: 304-455-2200 x3221
Fax: 304-455-6927
Jerry.Mullens@axiall.com

Br. 2

December 2, 2016

Certified Mail Return Receipt Requested

Licensing Assistance Team
Division of Nuclear Materials Safety
U. S. Nuclear Regulatory Commission, Region I
2100 Renaissance Boulevard, Suite 100
King of Prussia, Pennsylvania 19406-2713

REC'D 12/14/16 M0659

03006658

**Subject: Amendment to License No. 47-01542-01, Axiall Corporation,
Eagle Natrium LLC**

Attention: Licensing Assistance Team

Please find attached an amendment requested to the U.S. Nuclear Regulatory Commission Materials License No. 47-01542-01 for the Axiall Corporation, Eagle Natrium LLC Facility. The amendment is due to a change of personnel. Roni Williams has replaced Ryan Sapp as the primary Radiation Safety Officer. Additionally, Brian Habig has been trained as backup. Attached are copies of radiation training certificates for Roni Williams and Brian Habig.

If you have any questions regarding this information, please contact Roni Williams at (304) 455-2200, extension 3573.

Sincerely,

Jerry Mullens
Works Manager

Attachments:

592581

UNCLASSIFIED MATERIAL

December 2, 2016

AMENDMENT SUMMARY
U.S. NUCLEAR REGULATORY COMMISSION MATERIALS LICENSE NO. 47-01542-01

Section 12.

The Radiation Safety Officer for this license is ~~Ryan Sapp~~ Roni Williams.

Section 15.A.

Installation, initial radiation surveys, relocation, and removal from service of devices containing sealed sources shall be performed only by, R.J. Feldmeier, Roni Williams or Brian Habig ~~Ryan Sapp~~ in accordance with the manufacturer's instructions or by persons specifically licensed by the U.S. Nuclear Commission or an Agreement State to perform such services.

Section 16.

Prior to initial use and immediately after installation, relocation, dismantling, alignment, or any other activity involving the source or removal of the shielding, the licensee shall assure that a radiological survey is performed to determine radiation levels in accessible areas around, above, and below the gauge with the shutter open. This survey shall be performed only by Roni Williams ~~Ryan Sapp~~ or by persons authorized to perform such services by the U.S. Nuclear Regulatory Commission or an Agreement State. A record of the results of this survey shall be maintained for the duration of the license.

Roni Williams

Has successfully completed the 40 hour technical short course entitled


Radiation Safety Officer

November 14, 2016 - November 18, 2016

This certificate presented in Columbus, OH, on November 18, 2016

By Nevada Technical Associates, Inc.

Approval codes for CE units are: ASRT 30.5 units: NVZ0146001, AAHP 32 units: 2008-00-005, ABIH 4.5 units: 08-1362



Dr. Roger Sit
Instructor

Certificate Number: 1479157623010

Brian Habig

Has successfully completed the 40 hour technical short course entitled


Radiation Safety Officer

November 14, 2016 - November 18, 2016

This certificate presented in Columbus, OH, on November 18, 2016

By Nevada Technical Associates, Inc.

Approval codes for CE units are: ASRT 30.5 units: NVZ0146001, AAHP 32 units: 2008-00-005, ABIH 4.5 units: 08-1362



Dr. Roger Sit
Instructor

Certificate Number: 1479157623004



ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE

Name and Address of Applicant and/or Licensee James Mullens Works Manager Eagle Natrium, LLC P.O. Box 191 New Martinsville, West Virginia 26155-0191	Date December 20, 2016
	License Number(s) 47-01542-01
	Mail Control Number(s) 592581
	Licensing and/or Technical Reviewer or Branch Commercial, Industrial, R&D, and Academic Branch

This is to acknowledge receipt of your: ☒ Letter and/or ☐ Application Dated: December 2, 2016

The initial processing, which included an administrative review, has been performed.

☒ Amendment ☐ Termination ☐ New License ☐ Renewal

☒ There were no administrative omissions identified during our initial review.

☐ This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

☐ Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>
Follow the instructions on the form for submission.

☐ The following administrative omissions have been identified:

--

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

Region I
U. S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
2100 Renaissance Boulevard, Suite 100
King of Prussia, PA 19406-2713
(610) 337-5260, (610) 337-5313,
(610) 337-5398, (610) 337-5239