

# FEDERAL NOTIFICATION LETTER

Friday, December 30, 2016

Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

**From General Licensee:**

Bemidji Area Schools  
511 3<sup>rd</sup> St NW  
Bemidji MN 56601

**To Specific Licensee:**

SRB Technologies, Inc.  
2580 Landmark Drive  
Winston-Salem, NC 27103  
(336)-659-2610  
Radioactive Materials License #034-0534-2


<b>Date of Transfer:</b> (Enter Date Disposal Box was shipped to Specific Licensee)	01/10/2017
---	------------

**Description of Device(s) Transferred:**

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

<b>Printed Name:</b>	Steve Spindler
<b>Signature:</b>	
<b>Phone Number:</b>	218-333-3149

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

**SALES ORDER:** 1817210**CASE:** 29886

VEOLIA USE ONLY

**RGA #:** 996426**RGA # Expiration Date:** 03-21-17**UCN:** 1A51389B-6C53665D**FedEx Tracking #:** 691191700036287**Box # of #:** 1 of 1**TRITIUM EXIT SIGN INVENTORY FORM**

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	Saunders Roe Development	U20	53605	6-87	20
2.	Saunders Roe Development	U20	53606	6-87	20
3.	Saunders Roe Development	U20	53596	6-87	20
4.	Saunders Roe Development	U20	53595	6-87	20
5.	Everglo	A/15	5224	1-95	25
6.	Everglo	A/15	5227	1-95	25
7.					
8.					
9.					
10.					

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

**GENERATOR CERTIFICATION****Generator Signature:**

Steve Spindler

**Title:** Safety Manager**Print Name:**

Steve Spindler

**Date:** 12/16/2016 | 2:47 PM EST**VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX****Date Received:**

12/16/2016 | 4:52 PM EST

**Checked in by:**

Randi VanDinter

EE62131E1A0B4FD...

