



Donald W. Gregoire  
Columbia Generating Station  
P.O. Box 968, PE20  
Richland, WA 99352-0968  
Ph. 509.377.8616 | F. 509.377.4674  
dwgregoire@energy-northwest.com

February 1, 2017  
GO2-17-013

10 CFR 50.54(q)

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Subject: **COLUMBIA GENERATING STATION, DOCKET NO. 50-397;  
SUMMARY OF CHANGES AND ANALYSIS FOR REVISION 64 OF THE  
EMERGENCY PLAN and REVISION 20 OF EPIP 13.2.2 DETERMINING  
PROTECTIVE ACTION RECOMMENDATIONS**

Dear Sir or Madam:

Enclosed is the summary of changes and analysis for Revision 64 of the Emergency Plan and Revision 20 of PPM 13.2.2 Determining Protective Action Recommendations issued on January 4, 2017. The changes to the plan and Emergency Plan Implementing Procedure (EPIP) have been evaluated in accordance with 10 CFR 50.54(q) and 10 CFR 72.44(f). The Emergency Plan and EPIP, as revised, continues to meet the standards of 10 CFR 50.47(b) and the requirements of 10 CFR 50 Appendix E. Enclosure 1 contains a summary of changes and evaluations performed. Each change was evaluated in accordance with the station's 10 CFR 50.54(q) evaluation process. These changes do not create a reduction in effectiveness (RIE) of the approved emergency plan.

This submittal contains no new or revised regulatory commitments. Should you have any questions or desire additional information regarding these matters, please contact Charles R Forrester at (509) 377-2290.

Executed on the 1<sup>st</sup> day of February, 2017.

Respectfully,

D. W. Gregoire  
Manager, Regulatory Affairs and Performance Improvement

Enclosure: Summary of Changes and Analysis

cc: NRC Region IV Administrator  
NRC NRR Project Manager  
NRC Sr. Resident Inspector / 988C  
Director – Spent Fuel Storage & Transportation, NMSS  
CD Sonada, BPA / 1399 (email)  
WA Horin – Winston & Strawn (email)