



1



NOTES:  
1. LOGIC DIAGRAM LSK-9-10  
2. O-FAILS OPENS ON LOSS OF POWER.

PRC  
APERTURE  
CARD

LIMIT SWITCH DEVELOPMENT									
33		VALVE POSN		FUNCTION					
		FULL OPEN	FULL CLOSE	2SWP* AOV97A	2SWP* AOV97B				
1	A	—	—	GRN LT	GRN LT				
2	C	—	—	SPARE	SPARE				
3	E	—	—	SPARE	SPARE				
4	G	—	—	SPARE	SPARE				
5	A	—	—	RED LT	RED LT				
6	C	—	—	SPARE	SPARE				
7	E	—	—	SPARE	SPARE				
8	G	—	—	SPARE	SPARE				



NUCLEAR SAFETY RELATED  
QA CAT I, II

AC ELEM DIAG MISC AC CKT  
REAC BLDG VENT EMERG CLR VALVES  
NINE MILE POINT NUCLEAR STATION-UNIT 2  
NIAGARA MOHAWK POWER CORPORATION

STONE & WEBSTER ENGINEERING CORPORATION

i2177-ESK-7SWPIO

8	7	6	5	4	3	2	1