

PUBLIC SUBMISSION

As of: 2/1/17 3:49 PM
 Received: January 25, 2017
 Status: Pending Post
 Tracking No. 1k1-8ud0-x2e0
 Comments Due: February 21, 2017
 Submission Type: API

Docket: NRC-2016-0233

Pressurized Water Reactor Control Rod Ejection and Boiling Water Reactor Control Rod Drop Accidents

Comment On: NRC-2016-0233-0001

Pressurized Water Reactor Control Rod Ejection and Boiling Water Reactor Control Rod Drop Accidents;
 Request for Comment on Draft Regulatory Guide

Document: NRC-2016-0233-DRAFT-0002

Comment on FR Doc # 2016-27903

2

Submitter Information

Name: Pedro Perez

Address:

Lyon, France,

11/21/2016
 81FR83288

RECEIVED

RECEIVED

RECEIVED

General Comment

DG-1327 Section 4.4 makes reference to Regulatory Guide 1.183 for the steady-state fission product gap inventories. The new REA regulatory guide (DG-1327) should include these steady-state fission product gap inventories.

The new REA guide is welcome as it formalizes the guidance for the reactivity initiated accidents gap releases (among other criteria). The recommendation in this comment is constructive as it leads to a comprehensive regulatory guide for the REA and will be more efficient for the long-term. This comment recognizes that referencing RG-1.183 for the REA steady-state fission product gap inventory couples the new REA regulatory guide with a regulatory guide under revision. Regulatory Guide 1.183, Proposed Revision 1(DG-1199), is an on-going effort. This new REA guide (DG-1327) should stand be decoupled from RG-1.183.

SUNSI Review Complete

Template = ADM - 013

E-RIDS= ADM-03

Add= fclifford (PMC3)

E. O'Donnell (EXO)