

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Covanta Indianapolis, Inc. 2320 South Harding Street Indianapolis, Indiana 46221 REPORT NUMBER(S) 2017001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-38497	4. LICENSE NUMBER(S) 13-32836-01	5. DATE(S) OF INSPECTION January 25, 2017	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren		1/25/17
BRANCH CHIEF	Aaron T. McCraw		2/10/17

Docket File Information**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Covanta Indianapolis, Inc.
2320 South Harding Street
Indianapolis, Indiana 46221

REPORT NUMBER(S) 2017001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38497

4. LICENSE NUMBER(S)

13-32836-01

5. DATE(S) OF INSPECTION

January 25, 2017

6. INSPECTION PROCEDURES USED

87124

7. INSPECTION FOCUS AREAS

03.01 - 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

03120

2. PRIORITY

5

3. LICENSEE CONTACT

Brian Foster, Environmental Manager

4. TELEPHONE NUMBER

(317) 378-8726

☒ Main Office Inspection

Next Inspection Date: January 2022

☐ Field Office Inspection☐ Temporary Job Site Inspection**PROGRAM SCOPE**

This was an unannounced routine inspection of a waste management company. The licensee had previously possessed six fixed gauges as described on the license, each with a 100 mCi cesium-137 source, but had disposed of the devices in August 2016 through a licensed waste broker. The licensee had not yet received documentation of the final receipt of the devices at the disposal facility in Texas, but intended to request termination of the license once that documentation was received. The radiation safety officer remained employed at the facility, but the environmental manager was leading the effort to dispose of the gauges and terminate the license. The inspector briefed the environmental manager on the requirements in 10 CFR 30.36 concerning termination of licensed activities.

Performance Observations: The inspector reviewed documentation concerning the disposal of licensed materials, and noted no concerns with the documentation.

No violations were identified during this inspection.