

NINE MILE POINT
N.M.P. STATION

NMP-1115

NINE MILE POINT NUCLEAR STATION / P.O. BOX 32 LYCOMING, NEW YORK 13093 / TELEPHONE (315) 343-2110

April 30, 1979

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue -
King of Prussia, PA. 19406

RE: Docket No. 50-220
LER 79-05

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station #1 Technical Specifications 6.9.2 b(2), we hereby submit Licensee Event Report LER 79-05. The events reported will be further summarized in the periodic test report required by 10 CFR 50, Appendix J Section V.B.3 and Technical Specification Section 6.9.3e.

The events reported occurred when the Station was shutdown for refueling and overhaul. Repairs will be completed during the outage and the results of retest will be included in the referenced summary report.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President -
Electric Production

mtm

Attachment

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

7905070401

A002
S/
1/

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 4 0 1 7 9 8 0 5 0 1 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During periodic type C leakage test, found the following valves in
0 3 excess of Technical Specification: IV 68-06, IV 201-09, IV 201-10 and
0 4 IV 58.1-02. Repairs for these valves will be during this outage.
0 5
0 6
0 7
0 8

0 9 SYSTEM CODE S H 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE C 15 VALVE SUBCODE C 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 LER/RO REPORT NUMBER 7 9 21 22 EFFECT ON PLANT Z 20 35 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 22 37 40 ATTACHMENT SUBMITTED N 23 41 NP&D-4 FORM SUB. Y 24 42 PRIME COMP. SUPPLIER N 25 43 COMPONENT MANUFACTURER A 5 8 5 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Repairs will be completed during outage and the results of retest will
1 1 be included in Summary Report.
1 2
1 3
1 4

1 5 FACILITY STATUS H 28 29 % POWER 0 0 0 29 30 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 32 DISCOVERY DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 38 39 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2 0 PUBLICITY ISSUED N 44 45 DESCRIPTION NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER R. Jutras

PHONE: 315-343-2110 Ext. 1327

NRC USE ONLY